
APPROVED

2002-2004 STATE OF NEW MEXICO §303(d) LIST FOR ASSESSED RIVER/STREAM REACHES REQUIRING TOTAL MAXIMUM DAILY LOADS (TMDLs)

New Mexico Environment Department Surface Water Quality Bureau 1190 St. Francis Drive P.O. Box 26110 Santa Fe, New Mexico 87502

JUNE 2003



2002-2004 State of New Mexico 303d List **Table of Contents**

HUC: 11040001 Cimarron Headwaters

Carrizozo Creek (Dry Cimarron to headwaters)

Dry Cimarron River (Perennial reaches OK bnd to Oak Creek)

Long Canyon (Perennial reaches abv Dry Cimarron)

HUC: 11080001 Canadian Headwaters

Chicorica Creek (Canadian River to Raton Creek)

Lake Maloya

Raton Creek (Chicorica Creek to headwaters)

Stubblefield Lake

HUC: 11080002 Cimarron

Cieneguilla Creek (Eagle Nest Lake to headwaters)

Cimarron River (Canadian River to Cimarron)

Cimarron River (Cimarron to Turkey Creek)

Eagle Nest Lake

McCrystal Creek (North Ponil to headwaters)

Middle Ponil Creek (South Ponil to headwaters)

Moreno Creek (Eagle Nest Lake to headwaters) North Ponil Creek (South Ponil Creek to McCrystal Creek)

Ponil Creek (Cimarron River to confl of North & South Ponil)

Rayado Creek (Cimarron River to Miami Lake Diversion)

Sixmile Creek (Eagle Nest Lake to headwaters)

Springer Lake

HUC: 11080003 Upper Canadian

Charette Lake (Lower)

Conchas Reservoir

Manueles Creek (Ocate Creek to headwaters)

Ocate Creek (Ocate to Wheaton Creek)

HUC: 11080004 Mora

Coyote Creek (Mora River to Black Lake)

Little Coyote Creek (Black Lake to headwaters)

Mora River (Canadian River to Shoemaker)

Mora River (Rio la Casa to headwaters)

Morphy (Murphy) Lake

Rio la Casa (Mora River to confl of North and South Forks)

Sapello River (Mora River to Manuelitas Creek)

HUC: 11080006 Upper Canadian-Ute Reserv

Ute Reservoir

HUC: 11100101 Upper Beaver

Clayton Lake

HUC: 12050002 Blackwater Draw

Green Acres Lake

HUC: 12080001 Lost Draw

Lane Salt Lake

HUC: 13020101 Upper Rio Grande

Bitter Creek (Red River to headwaters)

Cabresto Creek (Red River to headwaters)

Cordova Creek (Costilla Creek to headwaters)

Costilla Creek (CO border to Diversion abv Costilla)

Embudo Creek (Rio Grande to Picuris Pueblo bnd)

Goose Lake

Guaje Canyon (San Ildefonso bnd to headwaters)

Little Tesuque Creek (Rio Tesuque to headwaters)

Los Alamos Canyon (San Ildefonso bnd to headwaters)

Los Alamos Reservoir

Pioneer Creek (Red River to headwaters)

Placer Creek (Red River to headwaters)

Pojoaque River (San Ildefonso bnd to Pojoaque bnd)

Pueblo Canyon (Los Alamos Canyon to headwaters)

Red River (Placer Creek to headwaters)

Red River (Rio Grande to Placer Creek)

Rendija Canyon (Guaje Canyon to headwaters)

Rio Chupadero (USFS bnd to headwaters)

Rio Fernando de Taos (Rio Pueblo de Taos to headwaters)

Rio Frijoles (Rio Medio to Pecos Wilderness)

Rio Grande (Red River to CO border)

Rio Grande (San Juan Pueblo bnd to Rio Pueblo de Taos)

Rio Grande del Rancho (Rio Pueblo de Taos to HWY 518)

Rio Hondo (Rio Grande to USFS bnd)

Rio Pueblo (Picuris Pueblo bnd to headwaters)

Rio Pueblo de Taos (Arroyo del Alamo to R Grande del Rancho)

Rio Pueblo de Taos (Rio Grande del Rancho to headwaters)

Rio Pueblo de Taos (Rio Grande to Arroyo del Alamo)

Rio Santa Barbara (Picuris Pueblo bnd to USFS bnd)

Santa Cruz River (San Juan Pueblo to Santa Cruz Dam)

Tesuque Creek (Little Tesuque Creek to confl of forks)

HUC: 13020102 Rio Chama

Abiquiu Creek (Rio Chama to headwaters)

Abiquiu Reservoir

Cañones Creek (Abiguiu Reservoir to headwaters)

Cecilia Canyon Creek (Rio Capulin to USFS bnd)

Chavez Creek (Rio Brazos to headwaters)

Chihuahuenos Creek (Cañones Creek to headwaters)

Clear Creek (Rio Gallina to headwaters)

Coyote Creek (Rio Puerco de Chama to headwaters)

El Rito Creek (Perennial reaches above El Rito)

El Vado Reservoir

Heron Reservoir

Hopewell Lake

Poleo Creek (Rio Puerco de Chama to headwaters)

Polvadera Creek (Cañones Creek to headwaters)

Rio Brazos (Rio Chama to Chavez Creek)

Rio Chama (Rio Brazos to Little Willow Creek)

Rio Chama (San Juan Pueblo to Abiquiu Dam)

Rio Chamita (Rio Chama to CO border)

Rio Gallina (Rio Capulin to headwaters)

Rio Nutrias (Rio Chama to headwaters)

Rio Ojo Caliente (Rio Chama to Rio Vallecitos)

Rio Puerco de Chama (Abiquiu Reservoir to Poleo Creek)

Rio Puerco de Chama (Poleo Creek to headwaters)

Rio Tusas (Rio Vallecitos to headwaters)

Rio Vallecitos (Rio Tusas to headwaters)

Rito de Tierra Àmarilla (Rio Chama to HWY 64)

Rito Resumidero (Rio Puerco de Chama to headwaters)

HUC: 13020201 Rio Grande-Santa Fe

Capulin Creek (Rio Grande to headwaters)

Galisteo Ck (Perennial reaches abv Santo Domingo bnd)

Las Huertas Creek (Placitas to Capulin Canyon)

Mortandad Canyon (San Ildefonso bnd to headwaters)

Pajarito Canyon (Rio Grande to headwaters)

Rito Cañon de los Frijoles (Rio Grande to headwaters)

Santa Fe River (Cochiti Pueblo bnd to Santa Fe WWTP)

Water Canyon (Rio Grande to headwaters)

HUC: 13020202 Jemez

Calaveras Creek (Rio Cebolla to headwaters)

Clear Creek (Rio de las Vacas to San Gregorio Lake)

Fenton Lake

Jemez River (East fork)

Jemez River (HWY 4 near Jemez Springs to East Fork)

Jemez River (Rio Guadalupe to HWY4 nr Jemez Springs)

Redondo Creek (Sulpher Creek to headwaters)

Rio Cebolla (Fenton Lake to headwaters)

Rio Cebolla (Rio de las Vacas to Fenton Lake)

Rio de las Vacas (Rio Cebolla to Rito de las Palomas)

Rio Guadalupe (Jemez River to confl with Rio Cebolla)

Rito Peñas Negras (Rio de las Vacas to headwaters)

San Antonio Creek (East Fork Jemez R to headwaters)

Sulphur Creek (Redondo Creek to headwaters)

HUC: 13020203 Rio Grande-Albuquerque

Rio Grande (Alameda Bridge to Santa Ana Pueblo bnd)

Rio Grande (Isleta Pueblo bnd to Alameda Street Bridge)

HUC: 13020204 Rio Puerco

Nacimiento Creek (USFS bnd to San Gregorio Reservoir)

Rio Puerco (Rito Olguin to headwaters)

Rito Leche (Perennial reaches above Rio Puerco)

San Pablo Canyon (Rio Puerco to headwaters)

HUC: 13020207 Rio San Jose

Bluewater Creek (Navajo Nation bnd to headwaters)

Bluewater Creek (Rio San Jose to Navajo Nation bnd)

Rio Moquino (Laguna Pueblo to Seboyettia Creek)

Rio Paguate (Laguna Pueblo bnd to headwaters)

HUC: 13020211 Elephant Butte Reservoir

Alamosa Creek (Perennial reaches abv Monticello diversion)

Elephant Butte Reservoir

HUC: 13030101 Caballo

Caballo Reservoir

Percha Creek (Perenniel reaches Caballo R to M Fork)

HUC: 13030202 Mimbres

Bear Canyon Reservoir

Cold Springs Creek (Hot Springs Creek to headwaters)

Gallinas Creek (Mimbres River to headwaters)

Hot Springs Creek (Mimbres River to headwaters)

Mimbres River (Perennial reaches below Sheppard Canyon)

Mimbres River (Sheppard Canyon to Cooney Campground)

HUC: 13050003 Tularosa Valley

Three Rivers (Perennial HWY 54 to USFS except Mescalero)

Tularosa Creek (Tularosa to Mescalero Apache bnd)

HUC: 13060001 Pecos Headwaters

Beaver Creek (Porvenir Creek to headwaters)

Cow Creek (Pecos River to headwaters)

Gallinas River (Las Vegas Diversion to headwaters)

Gallinas River (San Augustin to Las Vegas Diversion)

Holy Ghost Creek (Pecos River to headwaters) Pecos River (Alamitos Canyon to Willow Creek)

Pecos River (Canon del Oso to Alamitos Canyon)

Pecos River (Sumner Reservoir to Canon del Oso)

Rio Mora (Pecos River to headwaters)

Santa Rosa Reservoir

Sumner Reservoir

Tecolote Creek (Village of Tecolote to headwaters)

Willow Creek (Pecos River to headwaters)

Wright Canyon Creek (Tecolote Creek to headwaters)

HUC: 13060008 Rio Hondo

Alto Lake

Rio Bonito (Rio Ruidoso to Angus Canyon)

Rio Hondo (Perennial reaches Pecos R to Rio Ruidoso)

Rio Ruidoso (Rio Bonito to Seeping Springs Lake)

Rio Ruidoso (Seeping Springs Lake to Mescalero Apache bnd)

HUC: 13060010 Rio Peñasco

Rio Peñasco (HWY 24 to headwaters)

Rio Peñasco (Pecos River to HWY 24)

HUC: 13060011 Upper Pecos-Black

Avalon Reservoir

Black River (Pecos River to TX border)

Brantley Reservoir

Laguna Gatuna

Laguna Quatro

Laguna Tres

Laguna Uno

Pecos River (Black River to Tansil Lake)

Pecos River (TX border to Black River)

Sitting Bull Creek (Last Chance Canyon to Sitting Bull Spr)

Tansil Lake (Carlsbad Municipal Lake)

HUC: 14080101 Upper San Juan

Navajo Reservoir

San Juan River (Animas River to Cañon Largo)

San Juan River (Cañon Largo to Navajo Reservoir)

HUC: 14080104 Animas

Animas River (Estes Arroyo to CO border)

Animas River (San Juan River to Estes Arroyo)

Lake Farmington (Beeline Reservoir)

HUC: 14080105 Middle San Juan

La Plata River (San Juan River to CO border)

San Juan River (Navajo bnd at Hogback to Animas River)

HUC: 15020003 Carrizo Wash

Quemado Lake

HUC: 15020004 Zuni

McGaffey Lake

Rio Nutria (Zuni Pueblo bnd to headwaters)

HUC: 15040001 Upper Gila

Black Canyon Creek (East Fork Gila River to headwaters)

Canyon Creek (Middle Fork Gila River to headwaters)

Gila River (East Fork)

Gila River (Middle Fork)

Gila River (West Fork below Gila Cliff Dwellings)

Gilita Creek (Middle Fork to Willow Creek)

Lake Roberts

Mogollon Creek (Perennial reaches abv USGS gage)

Sapillo Creek (Gila River to Lake Roberts)

Taylor Creek (Beaver Creek to Wall Lake)

Taylor Creek (Perennial reaches aby Wall Lake)

Turkey Creek (Gila River to headwaters)

Wall Lake

Wile descent

HUC: 15040002 Upper Gila-Mangas

Mangas Creek (Gila River to Mangas Springs)

HUC: 15040004 San Francisco

Centerfire Creek (San Francisco R to headwaters)

Negrito Creek (South Fork)

Negrito Creek (Tularosa River to confl of N and S forks)

San Francisco River (Centerfire Creek to AZ border)

Tularosa River (San Francisco R to Apache Creek)

Whitewater Creek (San Francisco R to Whitewater Campgrd) Whitewater Creek (Whitewater Campgrd to headwaters)

2002-2004 State of New Mexico 303(d) List

For Assessed Surface Waters

HUC: 11040001 Cimarron Headwaters

Carrizozo Creek (Dry Cimarron to headwaters)

Cimarron Headwaters

Magnitude:

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2701_40	44.79	20.6.4.701	4	31-Dec-03 Proposed	No

Impaired Designated Use (s): Attainment status:

coldwater fishery Not supporting

Assessment information: Probable Causes of Impairment:

Dissolved oxygen Moderate
Aluminum - chronic Moderate

Probable Sources of Impairment:

Range grazing - Riparian and/or Upland

Natural Sources Hydromodification Grazing related Sources

Agriculture

Individual Active NPDES Permits:

TMDL (s) Completed:

Dry Cimarron River (Perennial reaches OK bnd to Oak Creek)

Cimarron Headwaters

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2701_00	77.65	20.6.4.701	4	31-Dec-03 Proposed	No

Impaired Designated Use (s): Attainment status: coldwater fishery Not supporting

Assessment information: Probable Causes of Impairment:

Probable Causes of Impairment:Magnitude:Total Dissolved SolidsModerateTemperatureModerate

Probable Sources of Impairment: Removal of Riparian Vegetation

Range grazing - Riparian and/or Upland

Natural Sources

Habitat Modification (other than Hydromodification)

Grazing related Sources

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

Long Canyon (Perennial reaches abv Dry Cimarron)

Cimarron Headwaters

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2701_20	8.21	20.6.4.701	4	31-Dec-03 Proposed	No

Impaired Designated Use (s): Attainment status:

coldwater fishery Not supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Temperature

Moderate

Probable Sources of Impairment: Removal of Riparian Vegetation

Range grazing - Riparian and/or Upland

Natural Sources

Habitat Modification (other than Hydromodification)

Grazing related Sources

Agriculture

Individual Active NPDES Permits:

HUC: 11080001

Canadian Headwaters

Chicorica Creek (Canadian River to Raton Creek)

Canadian Headwaters

	Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
Ī	NM-2305.A_250	9.47	20.6.4.305	8	31-Dec-17	No

Impaired Designated Use (s): Attainment status:

limited warmwater fishery Partially supporting

Assessment information: Probable Causes of Impairment:

Magnitude: Moderate

Plant Nutrients

Probable Sources of Impairment:Range grazing - Riparian and/or Upland

Grazing related Sources

Agriculture

Individual Active NPDES Permits:

TMDL (s) Completed:

Lake Maloya Canadian Headwaters

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2305.B_20	117.57	20.6.4.305	8	31-Dec-17	No

Impaired Designated Use (s): Attainment status:

limited warmwater fishery Not supporting coldwater fishery Not supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Mercury in fish tissue

Moderate

Probable Sources of Impairment:

Atmospheric Deposition

Individual Active NPDES Permits:

Raton Creek (Chicorica Creek to headwaters)

Canadian Headwaters

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2305.A 253	17.66	20.6.4.305	6	31-Dec-17	No

Impaired Designated Use (s): Attainment status:

limited warmwater fishery Partially supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Plant Nutrients

Moderate

Probable Sources of Impairment: Urban Runoff/Storm Sewers

Source Unknown

Range grazing - Riparian and/or Upland

Municipal Point Sources Grazing related Sources

Agriculture

Individual Active NPDES Permits:

Permit No: Permit Facility Name:

NM0029891 Raton, City of/Raton Water Works NM0026522 Raton Public Service Company

NM0020273 Raton, City of/WWTP

TMDL (s) Completed:

Stubblefield Lake Canadian Headwaters

	Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
ſ	NM-9000.B 101	907.96	unclassified	8	31-Dec-17	No

Impaired Designated Use (s): Attainment status: warmwater fishery Not supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Mercury in fish tissue

Moderate

Probable Sources of Impairment:

Atmospheric Deposition

Individual Active NPDES Permits:

HUC: 11080002 Cimarron

Cieneguilla Creek (Eagle Nest Lake to headwaters)

Cimarron

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2306.A_065	12.63	20.6.4.309	4	31-Dec-00	No

Impaired Designated Use (s): Attainment status:

high quality coldwater fishery Not supporting secondary contact Not supporting

Assessment information: Probable Causes of Impairment: Magnitude:

Turbidity Moderate
Stream Bottom Deposits Moderate
Fecal Coliform Moderate
Aluminum - chronic Moderate

Probable Sources of Impairment: Removal of Riparian Vegetation

Recreation and Tourism Activities (other than Boating -

see 7900)

Range grazing - Riparian and/or Upland

Natural Sources

Habitat Modification (other than Hydromodification)

Grazing related Sources

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

TMDL (s) Completed: TMDL for turbidity, SBD, fecal coliform, and Al chronic; de-list letter for temperature and total phosphorus

Cimarron River (Canadian River to Cimarron)

Cimarron

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2305.1.A_10	37.79	20.6.4.306	4	31-Dec-17	No

Impaired Designated Use (s): Attainment status:

warmwater fishery Partially supporting

Assessment information: Probable Causes of Impairment: Magnitude:

Aluminum - chronic Moderate

Probable Sources of Impairment:

Source Unknown

Range grazing - Riparian and/or Upland

Natural Sources

Grazing related Sources

Agriculture

Individual Active NPDES Permits:

TMDL (s) Completed: de-list letter for plant nutrients

Cimarron River (Cimarron to Turkey Creek)

Cimarron

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2306.A_040	4.25	20.6.4.309	4	31-Dec-17	No

Impaired Designated Use (s): Attainment status:
high quality coldwater fishery Partially supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Aluminum - chronic

Moderate

Probable Sources of Impairment:

Source Unknown

Recreation and Tourism Activities (other than Boating -

see 7900)

Range grazing - Riparian and/or Upland

Natural Sources

Grazing related Sources

Agriculture

Individual Active NPDES Permits:

TMDL (s) Completed: TMDL for Al-chronic; de-list letter for plant nutrients

Eagle Nest Lake Cimarron

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2306.B_00	1333.81	20.6.4.309	8	31-Dec-17	No

Impaired Designated Use (s):

high quality coldwater fishery

Not supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Mercury in fish tissue

Moderate

Probable Sources of Impairment:

Atmospheric Deposition

Individual Active NPDES Permits:

McCrystal Creek (North Ponil to headwaters)

Cimarron

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2306.A_112	6.81	20.6.4.309	4	31-Dec-00	No

Impaired Designated Use (s): Attainment status:
high quality coldwater fishery Partially supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Temperature

Moderate

Magnitude:

Probable Sources of Impairment: Removal of Riparian Vegetation

Habitat Modification (other than Hydromodification)

Individual Active NPDES Permits:

TMDL (s) Completed:

Middle Ponil Creek (South Ponil to headwaters)

Cimarron

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2306.A_121	20.99	20.6.4.309	4	31-Dec-00	No

Impaired Designated Use (s): Attainment status:

high quality coldwater fishery Not supporting

Assessment information: Probable Causes of Impairment:

Turbidity Moderate
Temperature Moderate
Stream Bottom Deposits Moderate

Probable Sources of Impairment:

Silviculture

Removal of Riparian Vegetation
Range grazing - Riparian and/or Upland
Logging Road Construction/Maintenance

Habitat Modification (other than Hydromodification)

Grazing related Sources

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

TMDL (s) Completed: TMDL for temperature, turbidity; de-list letter for total phosphorus

Moreno Creek (Eagle Nest Lake to headwaters)

Cimarron

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2306.A_060	9	20.6.4.309	4	31-Dec-00	No

Impaired Designated Use (s):

high quality coldwater fishery

Not supporting

Assessment information: Probable Causes of Impairment:

Probable Causes of Impairment:Magnitude:TurbidityModerateFecal ColiformModerate

Probable Sources of Impairment: Removal of Riparian Vegetation

Range grazing - Riparian and/or Upland

Habitat Modification (other than Hydromodification)

Grazing related Sources

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

TMDL (s) Completed: TMDL for turbidity and fecal coliform; de-list letter for plant nutrients

North Ponil Creek (South Ponil Creek to McCrystal Creek)

Cimarron

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2306.A_110	17.96	20.6.4.309	4	31-Dec-00	No

Impaired Designated Use (s): Attainment status:

high quality coldwater fishery Not supporting

Assessment information: Probable Causes of Impairment: Magnitude:

Turbidity Moderate
Temperature Moderate
Stream Bottom Deposits Moderate

Probable Sources of Impairment:

Silviculture

Removal of Riparian Vegetation

Range grazing - Riparian and/or Upland

Habitat Modification (other than Hydromodification)

Grazing related Sources

Agriculture

Individual Active NPDES Permits:

TMDL (s) Completed: TMDL for temp, turbidity, SBD, and total phosphorus; de-list letter for total phosphorus

Ponil Creek (Cimarron River to confl of North & South Ponil)

Cimarron

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2306.A_100	16.9	20.6.4.309	4	31-Dec-00	No

Impaired Designated Use (s): Attainment status: high quality coldwater fishery Not supporting

Assessment information: **Probable Causes of Impairment:**

Turbidity

Temperature

Aluminum - chronic

Magnitude: Moderate Moderate Stream Bottom Deposits Moderate Moderate

Probable Sources of Impairment: Removal of Riparian Vegetation

Range grazing - Riparian and/or Upland

Habitat Modification (other than Hydromodification)

Grazing related Sources

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

TMDL (s) Completed: TMDL for turbidity, temp, and Al chronic; de-list letter for total phosphorus

Rayado Creek (Cimarron River to Miami Lake Diversion)

Cimarron

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2305.3.A_80	14.24	20.6.4.307	8	31-Dec-01	No

Impaired Designated Use (s): Attainment status: warmwater fishery Partially supporting marginal coldwater fishery Partially supporting

Assessment information: **Probable Causes of Impairment:** Magnitude:

Stream Bottom Deposits Moderate

Probable Sources of Impairment: Removal of Riparian Vegetation Range grazing - Riparian and/or Upland Highway Maintenance and Runoff

Habitat Modification (other than Hydromodification)

Grazing related Sources

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

TMDL (s) Completed: TMDL for SBD

Sixmile Creek (Eagle Nest Lake to headwaters)

Cimarron

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2306.A_064	4.6	20.6.4.309	4	31-Dec-00	No

Impaired Designated Use (s): Attainment status:

high quality coldwater fishery Not supporting secondary contact Not supporting

Assessment information: Probable Causes of Impairment:

Probable Causes of Impairment:Magnitude:TurbidityModerateFecal ColiformModerate

Probable Sources of Impairment:

Onsite Wastewater Systems (Septic Tanks)
Off-farm Animal Holding/Management Area

Natural Sources Land Disposal

Intensive Animal Feeding Operations

Habitat Modification (other than Hydromodification)

Grazing related Sources

Agriculture

Individual Active NPDES Permits:

TMDL (s) Completed: TMDL for turbidity and fecal coliform; de-list for plant nutrients

Springer Lake Cimarron

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2305.1.B_10	458.85	20.6.4.306	8	31-Dec-17	No

Impaired Designated Use (s): Attainment status: warmwater fishery Not supporting

Assessment information: Probable Causes of Impairment: Magnitude:

Mercury in fish tissue Moderate

Probable Sources of Impairment:

Atmospheric Deposition

Individual Active NPDES Permits:

HUC: 11080003 Upper Canadian

Charette Lake (Lower)

Upper Canadian

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2305.5_10	300	20.6.4.308	8	31-Dec-17	No

Impaired Designated Use (s): Attainment status:

warmwater fishery Not supporting coldwater fishery Not supporting

Assessment information: Probable Causes of Impairment:

Probable Causes of Impairment: Magnitude:

Mercury in fish tissue Moderate

Probable Sources of Impairment:

Atmospheric Deposition

Individual Active NPDES Permits:

TMDL (s) Completed:

Conchas Reservoir Upper Canadian

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2304_00	4218.17	20.6.4.304	8	31-Dec-17	No

Impaired Designated Use (s): Attainment status:

warmwater fishery Not supporting

Assessment information: Probable Causes of Impairment: Magnitude:

Plant Nutrients Moderate
Mercury in fish tissue Moderate

Probable Sources of Impairment:

Source Unknown
Road/ Parking lot runoff
Removal of Riparian Vegetation
Range grazing - Riparian and/or Upland

Habitat Modification (other than Hydromodification)

Grazing related Sources

Bank or Shoreline Modification/Destabilization

Atmospheric Deposition

Agriculture

Individual Active NPDES Permits:

Manueles Creek (Ocate Creek to headwaters)

Upper Canadian

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2306.A 090	8.91	20.6.4.309	4	31-Dec-17	No

Impaired Designated Use (s): Attainment status:
high quality coldwater fishery Partially supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Cause Unknown

Moderate

Probable Sources of Impairment:

Source Unknown

Range grazing - Riparian and/or Upland Highway Maintenance and Runoff

Grazing related Sources

Agriculture

Individual Active NPDES Permits:

TMDL (s) Completed:

Ocate Creek (Ocate to Wheaton Creek)

Upper Canadian

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2306.A_070	14.49	20.6.4.309	4	31-Dec-17	No

Impaired Designated Use (s): Attainment status:
high quality coldwater fishery Partially supporting

Assessment information: Probable Causes of

Probable Causes of Impairment: Magnitude:
Cause Unknown Moderate

Probable Sources of Impairment:

Source Unknown

Range grazing - Riparian and/or Upland Highway Maintenance and Runoff

Grazing related Sources

Agriculture

Individual Active NPDES Permits:

HUC: 11080004 Mora

Coyote Creek (Mora River to Black Lake)

Mora

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2306.A_020	37.5	20.6.4.309	4	31-Dec-17	No

Impaired Designated Use (s): Attainment status:
high quality coldwater fishery Partially supporting

Assessment information: Probable Causes of Impairment:

Stream Bottom Deposits

Magnitude: Moderate

Probable Sources of Impairment:
Range grazing - Riparian and/or Upland

Highway Maintenance and Runoff Grazing related Sources

Agriculture

Individual Active NPDES Permits:

TMDL (s) Completed:

Little Coyote Creek (Black Lake to headwaters)

Mora

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2306.A_024	2.2	20.6.4.309	4	31-Dec-17	No

Impaired Designated Use (s):

high quality coldwater fishery

Not supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Moderate

Moderate

Moderate

Temperature Stream Bottom Deposits

Probable Sources of Impairment: Highway/Road/Bridge Construction

Construction

Turbidity

Individual Active NPDES Permits:

Mora River (Canadian River to Shoemaker)

Mora

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2305.A_020	50.14	20.6.4.305	7	31-Dec-17	No

Impaired Designated Use (s): Attainment status:

limited warmwater fishery Partially supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Lead - chronic

Moderate

Probable Sources of Impairment:

Source Unknown

Range grazing - Riparian and/or Upland

Grazing related Sources

Agriculture

Individual Active NPDES Permits:

TMDL (s) Completed: De-list letter for plant nutrients

Mora River (Rio la Casa to headwaters)

Mora

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2306.A_000	32.87	20.6.4.309	4	31-Dec-17	No

Impaired Designated Use (s): Attainment status:

high quality coldwater fishery Not supporting

Assessment information: Probable Causes of Impairment:

Magnitude: Moderate

Turbidity

Moderate

Stream Bottom Deposits

Probable Sources of Impairment:

Silviculture

Range grazing - Riparian and/or Upland

Grazing related Sources

Agriculture

Individual Active NPDES Permits:

Morphy (Murphy) Lake

Mora

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2305.3.B_30	50	20.6.4.307	8	31-Dec-17	No

Impaired Designated Use (s): Attainment status:

warmwater fishery Not supporting marginal coldwater fishery Not supporting

Assessment information: Probable Causes of Impairment:

Probable Causes of Impairment:Magnitude:Plant NutrientsModeratepHModerateDissolved oxygenModerateBottom DepositsModerate

Probable Sources of Impairment:

Silviculture

Recreation and Tourism Activities (other than Boating -

see 7900)

Range grazing - Riparian and/or Upland

Grazing related Sources

Agriculture

Individual Active NPDES Permits:

TMDL (s) Completed:

Rio la Casa (Mora River to confl of North and South Forks)

Mora

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2306.A_030	6.08	20.6.4.309	4	31-Dec-17	No

Impaired Designated Use (s): Attainment status:
high quality coldwater fishery Partially supporting

Assessment information: Probable Causes of Impairment:

Magnitude: Moderate

Stream Bottom Deposits

Probable Sources of Impairment: Removal of Riparian Vegetation

Hydromodification

Highway/Road/Bridge Construction Highway Maintenance and Runoff

Habitat Modification (other than Hydromodification)

Flow Regulation/Modification

Construction

Bank or Shoreline Modification/Destabilization

Individual Active NPDES Permits:

Sapello River (Mora River to Manuelitas Creek)

Mora

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2305.3.A_20	27.39	20.6.4.307	8	31-Dec-17	No

Impaired Designated Use (s): Attainment status:

warmwater fishery Partially supporting

marginal coldwater fishery Partially supporting

Assessment information: Probable Causes of Impairment:

Probable Causes of Impairment: Magnitude:
Cause Unknown Moderate

Probable Sources of Impairment:

Source Unknown

Range grazing - Riparian and/or Upland

Grazing related Sources

Agriculture

Individual Active NPDES Permits:

HUC: 11080006 Upper Canadian-Ute Reserv

Ute ReservoirUpper Canadian-Ute Reserv

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2302_00	3760.75	20.6.4.302	8	31-Dec-17	No

Impaired Designated Use (s): Attainment status: warmwater fishery Not supporting

Assessment information: Probable Causes of Impairment:

Probable Causes of Impairment:Magnitude:Mercury in fish tissueModerateBottom DepositsModerateAluminum - chronicModerate

Probable Sources of Impairment:

Road/ Parking lot runoff

Range grazing - Riparian and/or Upland

Grazing related Sources Atmospheric Deposition

Agriculture

Individual Active NPDES Permits:

HUC: 11100101 Upper Beaver

Clayton Lake Upper Beaver

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-9000.B_030	147.76	unclassified	8	31-Dec-17	No

Impaired Designated Use (s): Attainment status:

warmwater fishery Not supporting

Assessment information: Probable Causes of Impairment:

Probable Causes of Impairment: Magnitude:

Mercury in fish tissue Moderate

Probable Sources of Impairment:

Atmospheric Deposition

Individual Active NPDES Permits:

HUC: 12050002 Blackwater Draw

Green Acres Lake

Blackwater Draw

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-9000.B_046	10.94	unclassified	8	31-Dec-17	No

Impaired Designated Use (s): Attainment status:

wildlife habitat Not supporting marginal coldwater fishery Not supporting

Assessment information: Probable Causes of Impairment: Magnitude:

Plant Nutrients Moderate

Probable Sources of Impairment: Urban Runoff/Storm Sewers

Natural Sources

Individual Active NPDES Permits:

HUC: 12080001 Lost Draw

Lane Salt Lake Lost Draw

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-9000.B_072	400	unclassified	8	31-Dec-17	No

Impaired Designated Use (s): Attainment status:

wildlife habitat Not supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Toxic substances

Moderate

Probable Sources of Impairment:

Resource Extraction

Individual Active NPDES Permits:

HUC: 13020101 Upper Rio Grande

Bitter Creek (Red River to headwaters)

Upper Rio Grande

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2120.A_705	8.32	20.6.4.123	3	31-Dec-02 Proposed	No

Impaired Designated Use (s):

high quality coldwater fishery

Not supporting

Assessment information: Probable Causes of Impairment:

Magnitude: Moderate Moderate

Stream Bottom Deposits
Aluminum - acute

Probable Sources of Impairment:

Surface Mining Resource Extraction

Recreation and Tourism Activities (other than Boating -

see 7900) Natural Sources

Highway Maintenance and Runoff

Acid Mine Drainage

Individual Active NPDES Permits:

TMDL (s) Completed: TMDL for SBD and Al acute

Cabresto Creek (Red River to headwaters)

Upper Rio Grande

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2120.A_701	17.28	20.6.4.123	3	31-Dec-02 Proposed	No

Impaired Designated Use (s): Attainment status:
high quality coldwater fishery Not supporting

Assessment information: Probable Causes of Impairment:

Probable Causes of Impairment: Magnitude:
Aluminum - chronic Moderate

Probable Sources of Impairment:

Natural Sources

Highway Maintenance and Runoff

Individual Active NPDES Permits:

TMDL (s) Completed: TMDL for Al chronic

Cordova Creek (Costilla Creek to headwaters)

Upper Rio Grande

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2120.A 823	5.61	20.6.4.123	4	31-Dec-03 Proposed	No

Impaired Designated Use (s): Attainment status:
high quality coldwater fishery Partially supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Stream Bottom Deposits

Moderate

Probable Sources of Impairment: Removal of Riparian Vegetation

Recreation and Tourism Activities (other than Boating -

see 7900)

Highway Maintenance and Runoff

Habitat Modification (other than Hydromodification) Bank or Shoreline Modification/Destabilization

Individual Active NPDES Permits:

TMDL (s) Completed: TMDL for total phosphorus, SBD, and turbidity; de-list letter for total phosphorus

Costilla Creek (CO border to Diversion abv Costilla)

Upper Rio Grande

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2120.A_810	3.52	20.6.4.123	3	31-Dec-03 Proposed	No

Impaired Designated Use (s): Attainment status:

high quality coldwater fishery Partially supporting

Assessment information: Probable Causes of I

Magnitude:

Turbidity

Moderate

Probable Sources of Impairment:

Probable Causes of Impairment:

Range grazing - Riparian and/or Upland

Hydromodification

Highway Maintenance and Runoff

Grazing related Sources
Flow Regulation/Modification

Channelization Agriculture

Individual Active NPDES Permits:

Embudo Creek (Rio Grande to Picuris Pueblo bnd)

Upper Rio Grande

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2111_40	11.2	20.6.4.114	7	31-Dec-17	No

Impaired Designated Use (s): Attainment status:

marginal coldwater fishery Not supporting warmwater fishery Not supporting

Assessment information: Probable Causes of Impairment:

Probable Causes of Impairment:Magnitude:TurbidityModerateStream Bottom DepositsModerateAluminum - chronicModerate

Probable Sources of Impairment:

Vehicle use in arroyos

Removal of Riparian Vegetation

Range grazing - Riparian and/or Upland

Natural Sources Land Development Hydromodification

Habitat Modification (other than Hydromodification)

Grazing related Sources

Dredging
Construction
Channelization

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

Goose Lake Upper Rio Grande

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2120.B_12	5.95	20.6.4.123	8	31-Dec-17	No

Impaired Designated Use (s): Attainment status:

high quality coldwater fishery Not supporting

Assessment information: Probable Causes of Impairment:

Plant Nutrients Moderate
Bottom Deposits Moderate

Magnitude:

Probable Sources of Impairment: Removal of Riparian Vegetation

Recreation and Tourism Activities (other than Boating -

see 7900)

Range grazing - Riparian and/or Upland

Habitat Modification (other than Hydromodification)

Grazing related Sources

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

TMDL (s) Completed:

Guaje Canyon (San Ildefonso bnd to headwaters)

Upper Rio Grande

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-9000.A_005	12.33	unclassified	5	31-Dec-17	No

Impaired Designated Use (s): Attainment status:

livestock watering Not supporting wildlife habitat Not supporting

Assessment information: Probable Causes of Impairment:

Probable Causes of Impairment:Magnitude:Total Rec. SeleniumModerateGross AlphaModerate

Probable Sources of Impairment: Watershed runoff following forest fire

Natural Sources

Industrial Storm Water Sources Erosion and Sedimentation.

Individual Active NPDES Permits:

Little Tesuque Creek (Rio Tesuque to headwaters)

Upper Rio Grande

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2118.A_34	8.26	20.6.4.121	3	31-Dec-17	No

Impaired Designated Use (s): Attainment status:

high quality coldwater fishery Not supporting

Assessment information: Probable Causes of Impairment:

Probable Causes of Impairment:Magnitude:TurbidityModerateAluminum - acuteModerate

Probable Sources of Impairment:

Source Unknown

Removal of Riparian Vegetation

Recreation and Tourism Activities (other than Boating -

see 7900)

Hydromodification

Habitat Modification (other than Hydromodification)

Flow Regulation/Modification

Individual Active NPDES Permits:

TMDL (s) Completed:

Los Alamos Canyon (San Ildefonso bnd to headwaters)

Upper Rio Grande

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-9000.A_006	10.7	unclassified	5	31-Dec-17	No

Impaired Designated Use (s): Attainment status:

livestock watering Not supporting wildlife habitat Not supporting

Assessment information: Probable Causes of Impairment:

Probable Causes of Impairment:Magnitude:Total Rec. SeleniumModerateGross AlphaModerate

Probable Sources of Impairment: Watershed runoff following forest fire

Urban Runoff/Storm Sewers

Natural Sources Land Disposal

Industrial Storm Water Sources Industrial Point Sources Erosion and Sedimentation

Individual Active NPDES Permits: Permit No: Permit Facility Name:

NM0028355-004 USDOE Los Alamos Nat Labs Outfall 004

Los Alamos Reservoir Upper Rio Grande

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-9000.B_077	2	unclassified	8	31-Dec-17	No

Impaired Designated Use (s): Attainment status:

marginal coldwater fishery

wildlife habitat

Not supporting

livestock watering

Not supporting

Assessment information: Probable Causes of Impairment:

Magnitude: Moderate

Unknown toxicity

Probable Sources of Impairment:Watershed runoff following forest fire

Individual Active NPDES Permits:

TMDL (s) Completed:

Pioneer Creek (Red River to headwaters)

Upper Rio Grande

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2120.A_703	4.89	20.6.4.123	4	31-Dec-02 Proposed	No

Impaired Designated Use (s): Attainment status:
high quality coldwater fishery Not supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Turbidity

Moderate

Probable Sources of Impairment:

Subsurface Mining Resource Extraction

Removal of Riparian Vegetation

Recreation and Tourism Activities (other than Boating -

see 7900)

Habitat Modification (other than Hydromodification) Bank or Shoreline Modification/Destabilization

Abandoned mining

Individual Active NPDES Permits:

TMDL (s) Completed: TMDL for turbidity; de-list letter for SBD

Placer Creek (Red River to headwaters)

Upper Rio Grande

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2120.A_706	2.75	20.6.4.123	3	31-Dec-02 Proposed	No

Impaired Designated Use (s): Attainment status:
high quality coldwater fishery Partially supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Aluminum - acute

Moderate

Probable Sources of Impairment:

Resource Extraction

Removal of Riparian Vegetation

Placer Mining Natural Sources

Habitat Modification (other than Hydromodification) Bank or Shoreline Modification/Destabilization

Abandoned mining

Individual Active NPDES Permits:

TMDL (s) Completed: TMDL for Al acute; de-list for SBD

Pojoaque River (San Ildefonso bnd to Pojoaque bnd)

Upper Rio Grande

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2111_20	0.6	20.6.4.114	6	31-Dec-17	No

 Impaired Designated Use (s):
 Attainment status:

 warmwater fishery
 Partially supporting

 marginal coldwater fishery
 Partially supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Stream Bottom Deposits

Moderate

Probable Sources of Impairment:
Removal of Riparian Vegetation
Range grazing - Riparian and/or Upland

Hydromodification

Habitat Modification (other than Hydromodification)

Grazing related Sources Flow Regulation/Modification

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

Permit No: Permit Facility Name:

NM0028436 Pojoaque Terraces Mobile Home Park

Pueblo Canyon (Los Alamos Canyon to headwaters)

Upper Rio Grande

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-9000.A_043	9.17	unclassified	5	31-Dec-17	No

Impaired Designated Use (s): Attainment status:

livestock watering Not supporting wildlife habitat Partially supporting

Assessment information: Probable Causes of Impairment:

Probable Causes of Impairment:Magnitude:Total Rec. SeleniumModerateGross AlphaModerate

Probable Sources of Impairment: Watershed runoff following forest fire

Urban Runoff/Storm Sewers

Refuse disposal Natural Sources Land Disposal

Industrial Storm Water Sources

Hazardous Waste

Erosion and Sedimentation

Individual Active NPDES Permits:

TMDL (s) Completed:

Red River (Placer Creek to headwaters)

Upper Rio Grande

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2120.A_710	5.63	20.6.4.123	3	31-Dec-02 Proposed	No

Impaired Designated Use (s): Attainment status:

livestock watering Not supporting
high quality coldwater fishery Not supporting
irrigation Not supporting

Assessment information: Probable Causes of Impairment:

ent: Magnitude: Moderate

Aluminum - chronic

Probable Sources of Impairment:

Resource Extraction Natural Sources Mine Tailings Mill Tailings

Highway Maintenance and Runoff

Abandoned mining

Individual Active NPDES Permits:

TMDL (s) Completed: TMDL for Al chronic

Red River (Rio Grande to Placer Creek)

Upper Rio Grande

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2119_10	20.59	20.6.4.122	1	31-Dec-02 Proposed	No

Impaired Designated Use (s): Attainment status:

irrigation Not supporting coldwater fishery Not supporting livestock watering Not supporting

Assessment information: **Probable Causes of Impairment:**

Magnitude: Moderate

Aluminum - chronic

Probable Sources of Impairment:

Resource Extraction **Natural Sources** Mine Tailings Mill Tailings

Highway Maintenance and Runoff

Abandoned mining

Individual Active NPDES Permits:

Permit Facility Name: Permit No:

NM0030147 NMG&FD/Red River Fish Hatchery

NM0024899 Red River, Town of/WWTP

NM0022306 Molycorp-Questa

TMDL (s) Completed: TMDL for Al chronic

Rendija Canyon (Guaje Canyon to headwaters)

Upper Rio Grande

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-9000.A_045	8.13	unclassified	5	31-Dec-17	No

Impaired Designated Use (s): Attainment status: wildlife habitat Partially supporting

Assessment information: **Probable Causes of Impairment:**

Magnitude:

Total Rec. Selenium

Moderate

Probable Sources of Impairment: Watershed runoff following forest fire

Natural Sources

Industrial Storm Water Sources Erosion and Sedimentation.

Individual Active NPDES Permits:

Rio Chupadero (USFS bnd to headwaters)

Upper Rio Grande

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2118.A_40	4.28	20.6.4.121	3	31-Dec-17	No

Impaired Designated Use (s): Attainment status:

high quality coldwater fishery Not supporting

Assessment information: Probable Causes of Impairment:

Probable Causes of Impairment:Magnitude:TurbidityModerateStream Bottom DepositsModerateAluminum - acuteModerate

Probable Sources of Impairment:

Source Unknown

Recreation and Tourism Activities (other than Boating -

see 7900) Natural Sources

Highway Maintenance and Runoff

Individual Active NPDES Permits:

TMDL (s) Completed:

Rio Fernando de Taos (Rio Pueblo de Taos to headwaters)

Upper Rio Grande

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2120.A_512	21.6	20.6.4.123	3	31-Dec-03 Proposed	No

Impaired Designated Use (s): Attainment status:

high quality coldwater fishery Not supporting

Assessment information: Probable Causes of Impairment:

Probable Causes of Impairment:Magnitude:TemperatureModerateConductivityModerate

Probable Sources of Impairment:

Recreation and Tourism Activities (other than Boating -

see 7900)

Range grazing - Riparian and/or Upland Onsite Wastewater Systems (Septic Tanks)

Natural Sources Land Disposal Land Development

Highway Maintenance and Runoff

Habitat Modification (other than Hydromodification)

Grazing related Sources

Construction

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

Rio Frijoles (Rio Medio to Pecos Wilderness)

Upper Rio Grande

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2118.A 60	13.9	20.6.4.121	4	31-Dec-17	No

Impaired Designated Use (s): Attainment status:
high quality coldwater fishery Partially supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Cause Unknown

Moderate

Probable Sources of Impairment:

Source Unknown

Removal of Riparian Vegetation

Range grazing - Riparian and/or Upland

Habitat Modification (other than Hydromodification)

Grazing related Sources

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

TMDL (s) Completed:

Rio Grande (Red River to CO border)

Upper Rio Grande

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2119_05	27.75	20.6.4.122	2	31-Dec-03 Proposed	No

Impaired Designated Use (s): Attainment status: coldwater fishery Not supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Temperature

Moderate

рΗ

Moderate

Probable Sources of Impairment: Watershed runoff following forest fire

Removal of Riparian Vegetation

Recreation and Tourism Activities (other than Boating -

see 7900)

Hydromodification

Habitat Modification (other than Hydromodification)

Flow Regulation/Modification

Agriculture

Individual Active NPDES Permits:

Rio Grande (San Juan Pueblo bnd to Rio Pueblo de Taos)

Upper Rio Grande

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2111_10	29.64	20.6.4.114	7	31-Dec-17	No

Impaired Designated Use (s): Attainment status:

marginal coldwater fishery Not supporting warmwater fishery Not supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Turbidity

Moderate

Probable Sources of Impairment:

Removal of Riparian Vegetation

Range grazing - Riparian and/or Upland

Irrigated Crop Production

Habitat Modification (other than Hydromodification)

Grazing related Sources Crop-related Sources

Agriculture

Individual Active NPDES Permits:

Permit No: Permit Facility Name:

NM0029351 Espanola, City of

Rio Grande del Rancho (Rio Pueblo de Taos to HWY 518)

Upper Rio Grande

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2120.A_501	11.5	20.6.4.123	4	31-Dec-03 Proposed	No

Impaired Designated Use (s): Attainment status:

secondary contact Not supporting high quality coldwater fishery Not supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Conductivity

Moderate

Probable Sources of Impairment:

Range grazing - Riparian and/or Upland Onsite Wastewater Systems (Septic Tanks)

Natural Sources Land Disposal Hydromodification

Highway/Road/Bridge Construction Highway Maintenance and Runoff

Habitat Modification (other than Hydromodification)

Grazing related Sources Flow Regulation/Modification

Construction Channelization

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

Rio Hondo (Rio Grande to USFS bnd)

Upper Rio Grande

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2120.A_600	8.5	20.6.4.123	4	31-Dec-03 Proposed	No

Impaired Designated Use (s): Attainment status:
high quality coldwater fishery Partially supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Temperature

Moderate

Probable Sources of Impairment: Removal of Riparian Vegetation

Pasture grazing - Riparian and/or Upland

Irrigated Crop Production

Highway Maintenance and Runoff

Habitat Modification (other than Hydromodification)

Grazing related Sources
Crop-related Sources

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

TMDL (s) Completed: TMDL for nutrients

Upper Rio Grande

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2120.A_410	18.5	20.6.4.123	4	31-Dec-17	No

Impaired Designated Use (s): Attainment status:
high quality coldwater fishery Partially supporting

Rio Pueblo (Picuris Pueblo bnd to headwaters)

nigh quality colowater fishery Partially supporting

Assessment information: Probable Causes of Impairment:
Stream Bottom Deposits

Magnitude:Moderate

Probable Sources of Impairment: Removal of Riparian Vegetation

Recreation and Tourism Activities (other than Boating -

see 7900)

Range grazing - Riparian and/or Upland

Habitat Modification (other than Hydromodification)

Grazing related Sources

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

Rio Pueblo de Taos (Arroyo del Alamo to R Grande del Rancho)

Upper Rio Grande

	Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
ſ	NM-2119_30	1.2	20.6.4.122	2	31-Dec-03 Proposed	No

Impaired Designated Use (s): Attainment status: coldwater fishery Not supporting

irrigation Partially supporting

Assessment information: Probable Causes of Impairment:

Probable Causes of Impairment:Magnitude:TemperatureModerateStream Bottom DepositsModerate

Probable Sources of Impairment:

Range grazing - Riparian and/or Upland Onsite Wastewater Systems (Septic Tanks)

Municipal Point Sources

Land Disposal

Highway/Road/Bridge Construction Highway Maintenance and Runoff

Grazing related Sources Crop-related Sources

Construction Agriculture

Individual Active NPDES Permits:

TMDL (s) Completed:

Rio Pueblo de Taos (Rio Grande del Rancho to headwaters)

Upper Rio Grande

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2120.A_511	23.42	20.6.4.123	4	31-Dec-03 Proposed	No

Impaired Designated Use (s):

high quality coldwater fishery

Not supporting

Assessment information: Probable Causes of Impairment: Magnitude:

Temperature Moderate
Conductivity Moderate

Probable Sources of Impairment: Removal of Riparian Vegetation

Pasture grazing - Riparian and/or Upland

Irrigated Crop Production

Habitat Modification (other than Hydromodification)

Grazing related Sources Crop-related Sources

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

Rio Pueblo de Taos (Rio Grande to Arroyo del Alamo)

Upper Rio Grande

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2119_20	6.4	20.6.4.122	2	31-Dec-03 Proposed	No

Impaired Designated Use (s): Attainment status: coldwater fishery Not supporting

irrigation Partially supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Temperature

Moderate

Probable Sources of Impairment:

Urban Runoff/Storm Sewers

Recreation and Tourism Activities (other than Boating -

see 7900)

Range grazing - Riparian and/or Upland Pasture grazing - Riparian and/or Upland

Municipal Point Sources Irrigated Crop Production

Hydromodification

Highway Maintenance and Runoff

Habitat Modification (other than Hydromodification)

Grazing related Sources Flow Regulation/Modification

Crop-related Sources

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

Permit No: Permit Facility Name:

NM0024066 Taos, Town Of WWTP

Rio Santa Barbara (Picuris Pueblo bnd to USFS bnd)

Upper Rio Grande

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2120.A_419	7.39	20.6.4.123	4	31-Dec-17	No

Impaired Designated Use (s): Attainment status:
high quality coldwater fishery Partially supporting

Assessment information: Probable Causes of Impairment:

Probable Causes of Impairment: Magnitude:
Stream Bottom Deposits Moderate

Probable Sources of Impairment: Removal of Riparian Vegetation Range grazing - Riparian and/or Upland

Land Development Hydromodification

Habitat Modification (other than Hydromodification)

Grazing related Sources

Construction

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

TMDL (s) Completed:

Santa Cruz River (San Juan Pueblo to Santa Cruz Dam)

Upper Rio Grande

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2111_50	8.1	20.6.4.114	8	31-Dec-17	No

Impaired Designated Use (s): Attainment status:

livestock watering Not supporting irrigation Not supporting marginal coldwater fishery Not supporting warmwater fishery Not supporting

Assessment information: Probable Causes of Impairment:

Probable Causes of Impairment: Magnitude:
Turbidity Moderate

Stream Bottom Deposits Moderate

Probable Sources of Impairment:

Irrigated Crop Production

Hydromodification

Flow Regulation/Modification

Dam Construction Crop-related Sources

Agriculture

Individual Active NPDES Permits:

Tesuque Creek (Little Tesuque Creek to confl of forks)

Upper Rio Grande

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2118.A_31	1.44	20.6.4.121	3	31-Dec-17	No

Impaired Designated Use (s): Attainment status:

high quality coldwater fishery Not supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Turbidity

Moderate

Probable Sources of Impairment: Removal of Riparian Vegetation

Habitat Modification (other than Hydromodification)
Bank or Shoreline Modification/Destabilization

Individual Active NPDES Permits:

HUC: 13020102 Rio Chama

Abiquiu Creek (Rio Chama to headwaters)

Rio Chama

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2113_50	12.93	20.6.4.116	4	30-Jun-03 Proposed	No

Impaired Designated Use (s):

coldwater fishery

warmwater fishery

Attainment status:

Partially supporting

Partially supporting

Assessment information: Probable Causes of Impairment:

Probable Causes of Impairment:Magnitude:Stream Bottom DepositsModeratePlant NutrientsModerateDissolved oxygenModerate

Probable Sources of Impairment:

Range grazing - Riparian and/or Upland Onsite Wastewater Systems (Septic Tanks)

Land Disposal Hydromodification

Highway Maintenance and Runoff

Grazing related Sources

Channelization Agriculture

Individual Active NPDES Permits:

TMDL (s) Completed:

Abiquiu Reservoir Rio Chama

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2114_00	1038.35	20.6.4.117	8	31-Dec-17	No

 Impaired Designated Use (s):
 Attainment status:

 warmwater fishery
 Not supporting

 coldwater fishery
 Not supporting

Assessment information: Probable Causes of Impairment:

Probable Causes of Impairment: Magnitude:

Mercury in fish tissue Moderate

Probable Sources of Impairment:

Atmospheric Deposition

Individual Active NPDES Permits:

Cañones Creek (Abiquiu Reservoir to headwaters)

Rio Chama

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2116.A_010	17.44	20.6.4.119	3	30-Jun-03 Proposed	No

Impaired Designated Use (s): Attainment status:

high quality coldwater fishery

Not supporting
secondary contact

Partially supporting

Assessment information: Probable Causes of Impairment:

Probable Causes of Impairment:Magnitude:TurbidityModerateTemperatureModerateFecal ColiformModerateAluminum - chronicModerate

Probable Sources of Impairment:

Silviculture

Removal of Riparian Vegetation

Range grazing - Riparian and/or Upland Onsite Wastewater Systems (Septic Tanks)

Natural Sources Land Disposal

Harvesting, Restoration, Residue Management Habitat Modification (other than Hydromodification)

Grazing related Sources

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

TMDL (s) Completed:

Cecilia Canyon Creek (Rio Capulin to USFS bnd)

Rio Chama

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2116.A_042	5.05	20.6.4.119	4	30-Jun-03 Proposed	No

Impaired Designated Use (s): Attainment status:
high quality coldwater fishery Partially supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Stream Bottom Deposits

Moderate

Probable Sources of Impairment: Removal of Riparian Vegetation

Recreation and Tourism Activities (other than Boating -

see 7900)

Range grazing - Riparian and/or Upland

Habitat Modification (other than Hydromodification)

Grazing related Sources

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

Chavez Creek (Rio Brazos to headwaters)

Rio Chama

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2116.A_081	12.59	20.6.4.119	4	30-Jun-03 Proposed	No

Impaired Designated Use (s): Attainment status:

high quality coldwater fishery Not supporting

Assessment information: Probable Causes of Impairment:

Probable Causes of Impairment:Magnitude:TemperatureModeratePlant NutrientsModerate

Probable Sources of Impairment: Removal of Riparian Vegetation

Hydromodification

Habitat Modification (other than Hydromodification)

Dredging Channelization

Individual Active NPDES Permits:

TMDL (s) Completed:

Chihuahuenos Creek (Cañones Creek to headwaters)

Rio Chama

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2116.A_016	9.34	20.6.4.119	4	30-Jun-03 Proposed	No

Impaired Designated Use (s):

high quality coldwater fishery

Not supporting

Assessment information: Probable Causes of Impairment: Magnitude:

Stream Bottom Deposits Moderate

Probable Sources of Impairment:

Silviculture

Removal of Riparian Vegetation

Range grazing - Riparian and/or Upland

Habitat Modification (other than Hydromodification)

Grazing related Sources

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

Clear Creek (Rio Gallina to headwaters)

Rio Chama

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2116.A_043	3.55	20.6.4.119	4	30-Jun-03 Proposed	No

Impaired Designated Use (s):

high quality coldwater fishery

Not supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Stream Bottom Deposits

Moderate

Probable Sources of Impairment:

Silviculture

Range grazing - Riparian and/or Upland Logging Road Construction/Maintenance

Habitat Modification (other than Hydromodification)

Grazing related Sources

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

TMDL (s) Completed:

Coyote Creek (Rio Puerco de Chama to headwaters)

Rio Chama

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2116.A_022	13.7	20.6.4.119	4	30-Jun-03 Proposed	No

Impaired Designated Use (s):

high quality coldwater fishery

Not supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Stream Bottom Deposits

Moderate

Probable Sources of Impairment:

Removal of Riparian Vegetation Range grazing - Riparian and/or Upland Highway Maintenance and Runoff

Habitat Modification (other than Hydromodification)

Grazing related Sources

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

El Rito Creek (Perennial reaches above El Rito)

Rio Chama

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2112.A_20	13.17	20.6.4.115	3	30-Jun-03 Proposed	No

Impaired Designated Use (s): Attainment status:
high quality coldwater fishery Partially supporting

Assessment information: Probable Causes of Impairment:

Magnitude: Moderate Moderate

Plant Nutrients
Aluminum - chronic

Probable Sources of Impairment: Removal of Riparian Vegetation

Recreation and Tourism Activities (other than Boating -

see 7900)

Range grazing - Riparian and/or Upland

Irrigated Crop Production

Highway Maintenance and Runoff

Habitat Modification (other than Hydromodification)

Grazing related Sources Crop-related Sources

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

TMDL (s) Completed:

El Vado Reservoir Rio Chama

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2117_00	3222.27	20.6.4.120	8	31-Dec-17	No

Impaired Designated Use (s): Attainment status: coldwater fishery Not supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Mercury in fish tissue

Moderate

Probable Sources of Impairment:

Source Unknown

Recreation and Tourism Activities (other than Boating -

see 7900)

Range grazing - Riparian and/or Upland

Grazing related Sources Atmospheric Deposition

Agriculture

Individual Active NPDES Permits:

Heron Reservoir Rio Chama

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2117_10	4741.88	20.6.4.120	8	31-Dec-17	No

Impaired Designated Use (s): Attainment status:

coldwater fishery Not supporting

Assessment information: Probable Causes of Impairment:

Magnitude: Moderate

Mercury in fish tissue

Probable Sources of Impairment:

Source Unknown

Atmospheric Deposition

Individual Active NPDES Permits:

TMDL (s) Completed:

Hopewell Lake Rio Chama

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2112.B_00	16.13	20.6.4.115			No

Impaired Designated Use (s): Attainment status:
high quality coldwater fishery Partially supporting

Assessment information: Probable Causes of Impairment: Magnitude:

Plant Nutrients Moderate
Bottom Deposits Moderate

Probable Sources of Impairment:

Recreation and Tourism Activities (other than Boating -

see 7900)

Range grazing - Riparian and/or Upland

Habitat Modification (other than Hydromodification)

Grazing related Sources

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

Poleo Creek (Rio Puerco de Chama to headwaters)

Rio Chama

Asse	essment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NI	M-2116.A_023	12.16	20.6.4.119	4	30-Jun-03 Proposed	No

Impaired Designated Use (s): Attainment status:

high quality coldwater fishery Not supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Turbidity

Moderate

Probable Sources of Impairment:

Silviculture

Removal of Riparian Vegetation

Range grazing - Riparian and/or Upland

Natural Sources

Logging Road Construction/Maintenance

Habitat Modification (other than Hydromodification)

Grazing related Sources

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

TMDL (s) Completed:

Polvadera Creek (Cañones Creek to headwaters)

Rio Chama

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2116.A_011	13.94	20.6.4.119	4	30-Jun-03 Proposed	No

Impaired Designated Use (s): Attainment status:

high quality coldwater fishery Not supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Temperature

Moderate

Stream Bottom Deposits

Moderate

Probable Sources of Impairment: Removal of Riparian Vegetation

Range grazing - Riparian and/or Upland

Habitat Modification (other than Hydromodification)

Grazing related Sources

Agriculture

Individual Active NPDES Permits:

Rio Brazos (Rio Chama to Chavez Creek)

Rio Chama

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2116.A_080	3.52	20.6.4.119	4	30-Jun-03 Proposed	No

Impaired Designated Use (s): Attainment status:
high quality coldwater fishery Partially supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Temperature

Moderate

Magnitude:

Probable Sources of Impairment: Removal of Riparian Vegetation

Hydromodification

Habitat Modification (other than Hydromodification)

Dredging Channelization

Individual Active NPDES Permits:

TMDL (s) Completed:

Rio Chama (Rio Brazos to Little Willow Creek)

Rio Chama

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2116.A_001	11.72	20.6.4.119	4	31-Dec-03 Proposed	No

Impaired Designated Use (s): Attainment status:

high quality coldwater fishery Not supporting

Assessment information: Probable Causes of Impairment:

Temperature Moderate

Probable Sources of Impairment: Removal of Riparian Vegetation

Range grazing - Riparian and/or Upland

Municipal Point Sources Hydromodification

Habitat Modification (other than Hydromodification)

Grazing related Sources Flow Regulation/Modification

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

Rio Chama (San Juan Pueblo to Abiquiu Dam)

Rio Chama

As	ssessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
	NM-2113_00	28.3	20.6.4.116	7	30-Jun-03 Proposed	No

Impaired Designated Use (s): Attainment status:

warmwater fishery Not supporting coldwater fishery Not supporting

Assessment information: **Probable Causes of Impairment:**

Magnitude:

Aluminum - chronic

Moderate

Probable Sources of Impairment:

Range grazing - Riparian and/or Upland

Natural Sources

Irrigated Crop Production

Hydromodification **Grazing related Sources Dam Construction** Crop-related Sources

Agriculture

Individual Active NPDES Permits:

Permit No: Permit Facility Name:

NM0024830 Abiquiu MDWCA & MSWA

Rio Chamita (Rio Chama to CO border)

Rio Chama

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2116.A_110	13.68	20.6.4.119	2	30-Jun-03 Proposed	No

Impaired Designated Use (s):

high quality coldwater fishery

Not supporting

Assessment information: Probable Causes of Impairment:

Probable Causes of Impairment:Magnitude:Total AmmoniaModerateTemperatureModerateFecal ColiformModerateAluminum - chronicModerate

Probable Sources of Impairment: Removal of Riparian Vegetation

Range grazing - Riparian and/or Upland

Natural Sources

Municipal Point Sources Hydromodification

Habitat Modification (other than Hydromodification)

Grazing related Sources Flow Regulation/Modification

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

Permit No: Permit Facility Name:

NM0027731 Chama, Village of/WWTP

TMDL (s) Completed: TMDL for ammonia, total phosphorus, fecal coliform, temp; de-list for total phosphorus

Rio Gallina (Rio Capulin to headwaters)

Rio Chama

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2116.A_040	8.77	20.6.4.119	4	30-Jun-03 Proposed	No

Impaired Designated Use (s):

high quality coldwater fishery

Not supporting

Assessment information: Probable Causes of Impairment:

Probable Causes of Impairment: Magnitude:
Stream Bottom Deposits Moderate

Probable Sources of Impairment: Removal of Riparian Vegetation Range grazing - Riparian and/or Upland

Highway Maintenance and Runoff Habitat Modification (other than Hydromodification)

Grazing related Sources

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

Rio Nutrias (Rio Chama to headwaters)

Rio Chama

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2116.A_060	34.63	20.6.4.119	4	30-Jun-03 Proposed	No

Impaired Designated Use (s): Attainment status:

high quality coldwater fishery Not supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Turbidity

Moderate

Probable Sources of Impairment:
Removal of Riparian Vegetation
Range grazing - Riparian and/or Upland

Irrigated Crop Production

Habitat Modification (other than Hydromodification)

Grazing related Sources Crop-related Sources

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

TMDL (s) Completed:

Rio Ojo Caliente (Rio Chama to Rio Vallecitos)

Rio Chama

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2113_10	22.33	20.6.4.116	7	30-Jun-03 Proposed	No

Impaired Designated Use (s): Attainment status: warmwater fishery Not supporting

coldwater fishery Not supporting

Assessment information: Probable Causes of Impairment:

Magnitude: Moderate

Stream Bottom Deposits
Aluminum - chronic

Moderate

Probable Sources of Impairment:

Removal of Riparian Vegetation

Recreation and Tourism Activities (other than Boating -

see 7900)

Range grazing - Riparian and/or Upland

Natural Sources

Irrigated Crop Production

Hydromodification

Habitat Modification (other than Hydromodification)

Grazing related Sources Crop-related Sources Channelization

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

Rio Puerco de Chama (Abiquiu Reservoir to Poleo Creek)

Rio Chama

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2115_20	8.81	20.6.4.118	4	30-Jun-03 Proposed	No

Impaired Designated Use (s): Attainment status: coldwater fishery Partially supporting

warmwater fishery Partially supporting

Assessment information: Probable Causes of Impairment:

Probable Causes of Impairment:Magnitude:TemperatureModerateFecal ColiformModerate

Probable Sources of Impairment: Removal of Riparian Vegetation

Range grazing - Riparian and/or Upland Onsite Wastewater Systems (Septic Tanks)

Land Disposal

Habitat Modification (other than Hydromodification)

Grazing related Sources

Agriculture

Individual Active NPDES Permits:

TMDL (s) Completed:

Rio Puerco de Chama (Poleo Creek to headwaters)

Rio Chama

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2116.A_020	12.2	20.6.4.119	4	30-Jun-03 Proposed	No

Impaired Designated Use (s):

high quality coldwater fishery

Not supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Stream Bottom Deposits

Moderate

Probable Sources of Impairment:

Silviculture

Removal of Riparian Vegetation

Natural Sources

Harvesting, Restoration, Residue Management Habitat Modification (other than Hydromodification) Forest Management (pumped drainage, fertilization,

pesticide application)

Bank or Shoreline Modification/Destabilization

Individual Active NPDES Permits:

Rio Tusas (Rio Vallecitos to headwaters)

Rio Chama

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2113_30	42.9	20.6.4.116	4	30-Jun-03 Proposed	No

Impaired Designated Use (s): Attainment status:

coldwater fishery Not supporting warmwater fishery Not supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Stream Bottom Deposits

Moderate

Probable Sources of Impairment:

Removal of Riparian Vegetation

Range grazing - Riparian and/or Upland

Habitat Modification (other than Hydromodification)

Grazing related Sources

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

Rio Vallecitos (Rio Tusas to headwaters)

Rio Chama

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2112.A_00	36.31	20.6.4.115	4	30-Jun-03 Proposed	No

Impaired Designated Use (s): Attainment status:

high quality coldwater fishery Not supporting

Assessment information: Probable Causes of Impairment:

Probable Causes of Impairment:Magnitude:TurbidityModerateTemperatureModerateAluminum - chronicModerateAluminum - acuteModerate

Probable Sources of Impairment:

Surface Mining Resource Extraction

Removal of Riparian Vegetation

Recreation and Tourism Activities (other than Boating -

see 7900)

Range grazing - Riparian and/or Upland

Irrigated Crop Production

Hydromodification

Highway Maintenance and Runoff

Habitat Modification (other than Hydromodification)

Grazing related Sources Crop-related Sources

Channelization

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

Rito de Tierra Amarilla (Rio Chama to HWY 64)

Rio Chama

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2116.A_070	15.8	20.6.4.119	4	30-Jun-03 Proposed	No

Impaired Designated Use (s): Attainment status:

high quality coldwater fishery Not supporting

Assessment information: **Probable Causes of Impairment:**

Magnitude: Turbidity Moderate Temperature Moderate Stream Bottom Deposits Moderate

Probable Sources of Impairment: Removal of Riparian Vegetation Range grazing - Riparian and/or Upland Highway Maintenance and Runoff

Habitat Modification (other than Hydromodification)

Grazing related Sources

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

TMDL (s) Completed:

Rito Resumidero (Rio Puerco de Chama to headwaters)

Rio Chama

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2116.A_025	2.75	20.6.4.119	4	30-Jun-03 Proposed	No

Impaired Designated Use (s): Attainment status: high quality coldwater fishery Partially supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Stream Bottom Deposits

Moderate

Probable Sources of Impairment:

Silviculture

Removal of Riparian Vegetation

Range grazing - Riparian and/or Upland Logging Road Construction/Maintenance Harvesting, Restoration, Residue Management Habitat Modification (other than Hydromodification)

Grazing related Sources

Forest Management (pumped drainage, fertilization,

pesticide application)

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

HUC: 13020201 Rio Grande-Santa Fe

Capulin Creek (Rio Grande to headwaters)

Rio Grande-Santa Fe

Magnitude:

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2118.A_72	13.14	20.6.4.121	4	31-Dec-17	No

Impaired Designated Use (s): Attainment status: high quality coldwater fishery Partially supporting

Assessment information: **Probable Causes of Impairment:**

Turbidity

Stream Bottom Deposits

Moderate Moderate

Probable Sources of Impairment: Watershed runoff following forest fire

Silviculture

Harvesting, Restoration, Residue Management

Individual Active NPDES Permits:

TMDL (s) Completed:

Galisteo Ck (Perennial reaches abv Santo Domingo bnd)

Rio Grande-Santa Fe

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2118.A_10	43.5	20.6.4.121	8	31-Dec-17	No

Impaired Designated Use (s): Attainment status: high quality coldwater fishery Partially supporting

Assessment information: **Probable Causes of Impairment:**

Magnitude: Stream Bottom Deposits Moderate

Probable Sources of Impairment: Removal of Riparian Vegetation Range grazing - Riparian and/or Upland

Hydromodification

Habitat Modification (other than Hydromodification)

Grazing related Sources

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

Permit Facility Name: Permit No: NM0028711 Lac Minerals Inc

Las Huertas Creek (Placitas to Capulin Canyon)

Rio Grande-Santa Fe

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2108.5_00	15.5	20.6.4.111	4	31-Dec-17	No

Impaired Designated Use (s): Attainment status: coldwater fishery Partially supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Stream Bottom Deposits

Moderate

Probable Sources of Impairment:

Road/ Parking lot runoff

Removal of Riparian Vegetation

Recreation and Tourism Activities (other than Boating -

see 7900)

Highway Maintenance and Runoff

Habitat Modification (other than Hydromodification) Bank or Shoreline Modification/Destabilization

Individual Active NPDES Permits:

TMDL (s) Completed:

Mortandad Canyon (San Ildefonso bnd to headwaters)

Rio Grande-Santa Fe

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-9000.A_042	4.27	unclassified	5	31-Dec-17	No

Impaired Designated Use (s): Attainment status:

livestock watering Not supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Gross Alpha

Moderate

Probable Sources of Impairment: Watershed runoff following forest fire

Urban Runoff/Storm Sewers

Natural Sources Land Disposal

Industrial Storm Water Sources Industrial Point Sources Erosion and Sedimentation

Individual Active NPDES Permits:

Permit No: Permit Facility Name:

NM0028355-002 USDOE Los Alamos Nat Labs Outfall 002

Pajarito Canyon (Rio Grande to headwaters)

Rio Grande-Santa Fe

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-9000.A_040	13.3	unclassified	5	31-Dec-17	No

Impaired Designated Use (s): Attainment status:

livestock watering Not supporting wildlife habitat Not supporting

Assessment information: Probable Causes of Impairment:

Probable Causes of Impairment:Magnitude:Total Rec. SeleniumModerateGross AlphaModerate

Probable Sources of Impairment: Watershed runoff following forest fire

Urban Runoff/Storm Sewers

Natural Sources Land Disposal

Industrial Point Sources
Erosion and Sedimentation

Individual Active NPDES Permits:

TMDL (s) Completed:

Rito Cañon de los Frijoles (Rio Grande to headwaters)

Rio Grande-Santa Fe

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2118.A_70	11.56	20.6.4.121	3	31-Dec-17	No

Impaired Designated Use (s):

high quality coldwater fishery

Partially supporting

Assessment information: Probable Causes of Impairment:

Probable Causes of Impairment: Magnitude:
Pesticides -- DDT Moderate

Probable Sources of Impairment:

Spills

Land Disposal

Individual Active NPDES Permits:

Santa Fe River (Cochiti Pueblo bnd to Santa Fe WWTP)

Rio Grande-Santa Fe

Magnitude:

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2110_00	17.56	20.6.4.113	6	31-Dec-99	No

Impaired Designated Use (s): Attainment status:

marginal coldwater fishery Not supporting

warmwater fishery Not supporting

Assessment information: Probable Causes of Impairment:

Stream Bottom Deposits Moderate

Probable Sources of Impairment:

Urban Runoff/Storm Sewers

Surface Mining Resource Extraction

Range grazing - Riparian and/or Upland

Municipal Point Sources

Mine Tailings

Grazing related Sources

Agriculture

Individual Active NPDES Permits:

Permit No: Permit Facility Name:

NM0030368 Ranchland Utility Company NM0022292 Santa Fe, City of/WWTP

TMDL (s) Completed: TMDL for SBD, DO, pH, and chlorine; de-list letter for plant nutrients

Water Canyon (Rio Grande to headwaters)

Rio Grande-Santa Fe

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-9000.A_044	11.05	unclassified	5	31-Dec-17	No

Impaired Designated Use (s): Attainment status:

livestock watering Not supporting wildlife habitat Not supporting

Assessment information: Probable Causes of Impairment:

Probable Causes of Impairment:Magnitude:Total Rec. SeleniumModerateGross AlphaModerate

Probable Sources of Impairment: Watershed runoff following forest fire

Natural Sources Land Disposal

Industrial Storm Water Sources Industrial Point Sources Erosion and Sedimentation.

Individual Active NPDES Permits:

Permit No: Permit Facility Name:

NM0028355-003 USDOE Los Alamos Nat Labs Outfall 003

HUC: 13020202 Jemez

Calaveras Creek (Rio Cebolla to headwaters)

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2106.A_53	9.2	20.6.4.108	4	31-Dec-02 Proposed	No

Impaired Designated Use (s): Attainment status: high quality coldwater fishery Not supporting

Assessment information: **Probable Causes of Impairment:**

Magnitude:

Stream Bottom Deposits

Moderate

Probable Sources of Impairment: Highway Maintenance and Runoff

Individual Active NPDES Permits:

TMDL (s) Completed:

Clear Creek (Rio de las Vacas to San Gregorio Lake)

Jemez

Jemez

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2106.A_54	8.92	20.6.4.108	4	31-Dec-02 Proposed	No

Impaired Designated Use (s): Attainment status: high quality coldwater fishery Not supporting

Assessment information: **Probable Causes of Impairment:**

Magnitude:

Turbidity

Moderate

Probable Sources of Impairment:

Source Unknown **Natural Sources**

Habitat Modification (other than Hydromodification) Bank or Shoreline Modification/Destabilization

Individual Active NPDES Permits:

TMDL (s) Completed: TMDL for turbidity and TOC Fenton Lake Jemez

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2106.B_00	23.81	20.6.4.108	8	31-Dec-17	No

Impaired Designated Use (s): Attainment status:

high quality coldwater fishery Not supporting

Assessment information: Probable Causes of Impairment:

Magnitude: Moderate Moderate

Magnitude:

Plant Nutrients
Bottom Deposits

Probable Sources of Impairment: Removal of Riparian Vegetation

Recreation and Tourism Activities (other than Boating -

see 7900)

Range grazing - Riparian and/or Upland Onsite Wastewater Systems (Septic Tanks)

Land Disposal

Highway Maintenance and Runoff

Habitat Modification (other than Hydromodification)

Grazing related Sources

Agriculture

Individual Active NPDES Permits:

TMDL (s) Completed:

Jemez River (East fork)

Jemez

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2106.A_10	19.03	20.6.4.108	4	31-Dec-02 Proposed	No

Impaired Designated Use (s): Attainment status:

high quality coldwater fishery Partially supporting

Assessment information:

Probable Causes of Impairment:

Turbidity Moderate

Probable Sources of Impairment:

Silviculture

Recreation and Tourism Activities (other than Boating -

see 7900)

Range grazing - Riparian and/or Upland Harvesting, Restoration, Residue Management Habitat Modification (other than Hydromodification)

Grazing related Sources

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

TMDL (s) Completed: TMDL for turbidity

Jemez River (HWY 4 near Jemez Springs to East Fork)

Jemez

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2106.A_00	3.4	20.6.4.108	1	31-Dec-02 Proposed	No

Impaired Designated Use (s): Attainment status:

livestock watering Partially supporting
high quality coldwater fishery Partially supporting
fish culture Partially supporting

Assessment information: Probable Causes of Impairment:

Probable Causes of Impairment:Magnitude:TurbidityModerateStream Bottom DepositsModerateAluminum - acuteModerate

Probable Sources of Impairment:

Removal of Riparian Vegetation

Recreation and Tourism Activities (other than Boating -

see 7900)

Range grazing - Riparian and/or Upland

Natural Sources Land Development

Highway Maintenance and Runoff

Habitat Modification (other than Hydromodification)

Grazing related Sources

Construction

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

TMDL (s) Completed: TMDL for Al acute, turbidity, and SBD; de-list letter for plant nutrients

Jemez River (Rio Guadalupe to HWY4 nr Jemez Springs)

Jemez

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2105.5_10	9.67	20.6.4.107	1	31-Dec-02 Proposed	No

Impaired Designated Use (s): Attainment status:

livestock watering Partially supporting

coldwater fishery Partially supporting

Assessment information: Probable Causes of Impairment: Magnitude:

Turbidity Moderate
Stream Bottom Deposits Moderate
Aluminum - acute Moderate

Probable Sources of Impairment:

Source Unknown

Removal of Riparian Vegetation

Recreation and Tourism Activities (other than Boating -

see 7900)

Range grazing - Riparian and/or Upland

Natural Sources Land Development

Highway Maintenance and Runoff

Habitat Modification (other than Hydromodification)

Grazing related Sources

Construction

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

Permit No: Permit Facility Name:

NM0028011 Jemez Springs, Village of/WWTP

TMDL (s) Completed: TMDL for Al acute, turbidity, and SBD; de-list letter for plant nutrients

Redondo Creek (Sulpher Creek to headwaters)

Jemez

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2106.A_21	6.2	20.6.4.108	4	31-Dec-02 Proposed	No

Impaired Designated Use (s): Attainment status:

high quality coldwater fishery Not supporting

Assessment information: Probable Causes of Impairment:

Turbidity

Temperature

sirment: Magnitude:

Moderate

Moderate

Probable Sources of Impairment: Road Maintenance and Runoff Removal of Riparian Vegetation

Range grazing - Riparian and/or Upland

Habitat Modification (other than Hydromodification)

Grazing related Sources

Agriculture

Individual Active NPDES Permits:

TMDL (s) Completed: TMDL for turbidity, total phosphorus, and temperature; de-list letter for total phosphorus

Rio Cebolla (Fenton Lake to headwaters)

Jemez

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2106.A_52	14.63	20.6.4.108	2	31-Dec-02 Proposed	No

Impaired Designated Use (s): Attainment status:

high quality coldwater fishery Not supporting

Assessment information: Probable Causes of Impairment: Magnitude:

Temperature Moderate
Stream Bottom Deposits Moderate

Probable Sources of Impairment: Removal of Riparian Vegetation

Recreation and Tourism Activities (other than Boating -

see 7900)

Range grazing - Riparian and/or Upland Intensive Animal Feeding Operations Highway Maintenance and Runoff

Habitat Modification (other than Hydromodification)

Grazing related Sources

Aquaculture Agriculture

Individual Active NPDES Permits:

TMDL (s) Completed: TMDL for temperature and SBD

Rio Cebolla (Rio de las Vacas to Fenton Lake)

Jemez

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2106.A_50	6.07	20.6.4.108	4	31-Dec-02 Proposed	No

Impaired Designated Use (s): Attainment status:
high quality coldwater fishery Not supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Stream Bottom Deposits

Moderate

Probable Sources of Impairment:

Recreation and Tourism Activities (other than Boating -

see 7900)

Range grazing - Riparian and/or Upland Highway Maintenance and Runoff

Grazing related Sources

Agriculture

Individual Active NPDES Permits:

Permit No: Permit Facility Name:

NM0030112 NMG&FD/Seven Springs Fish Hatchery

TMDL (s) Completed: TMDL for SBD

Rio de las Vacas (Rio Cebolla to Rito de las Palomas)

Jemez

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2106.A_40	13.42	20.6.4.108	3	31-Dec-02 Proposed	No

Impaired Designated Use (s): Attainment status:

high quality coldwater fishery

Not supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Temperature

Moderate

Probable Sources of Impairment:

Removal of Riparian Vegetation

Range grazing - Riparian and/or Upland

Habitat Modification (other than Hydromodification)

Grazing related Sources

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

TMDL (s) Completed: TMDL for temperature and TOC

Rio Guadalupe (Jemez River to confl with Rio Cebolla)

Jemez

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2106.A_30	12.65	20.6.4.108	3	31-Dec-02 Proposed	No

Impaired Designated Use (s): Attainment status:

high quality coldwater fishery Partially supporting

Assessment information: Probable Causes of Impairment:

Magnitude: Moderate

Aluminum - chronic

Moderate

Probable Sources of Impairment:

Removal of Riparian Vegetation

Recreation and Tourism Activities (other than Boating -

see 7900)

Turbidity

Range grazing - Riparian and/or Upland

Natural Sources

Habitat Modification (other than Hydromodification)

Grazing related Sources

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

TMDL (s) Completed: TMDL for Al chronic, turbidity, and SBD; de-list letter for total phosphorus

Rito Peñas Negras (Rio de las Vacas to headwaters)

Jemez

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2106.A_42	11.78	20.6.4.108	4	31-Dec-02 Proposed	No

Impaired Designated Use (s):

Attainment status:

high quality coldwater fishery

Partially supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Temperature

Moderate Moderate

Stream Bottom Deposits

Probable Sources of Impairment: Removal of Riparian Vegetation

Range grazing - Riparian and/or Upland

Highway Maintenance and Runoff

Habitat Modification (other than Hydromodification)

Grazing related Sources

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

TMDL (s) Completed: TMDL for temperature, TOC, and SBD

San Antonio Creek (East Fork Jemez R to headwaters)

Jemez

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2106.A_20	24.75	20.6.4.108	4	31-Dec-02 Proposed	No

Impaired Designated Use (s): Attainment status:

high quality coldwater fishery Partially supporting

Assessment information: Probable Causes of Impairment:

Probable Causes of Impairment:Magnitude:TurbidityModerateTemperatureModerate

Probable Sources of Impairment:

Silviculture

Removal of Riparian Vegetation

Recreation and Tourism Activities (other than Boating -

see 7900)

Range grazing - Riparian and/or Upland

Natural Sources

Logging Road Construction/Maintenance

Land Development

Habitat Modification (other than Hydromodification)

Grazing related Sources

Construction

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

TMDL (s) Completed: TMDL for turbidity and temperature

Sulphur Creek (Redondo Creek to headwaters)

Jemez

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2106.A_22	6.1	20.6.4.108	4	31-Dec-02 Proposed	No

Impaired Designated Use (s):

high quality coldwater fishery

Not supporting

Assessment information: Probable Causes of Impairment:

Magnitude: Moderate Moderate

pH Conductivity

Probable Sources of Impairment:

Source Unknown

Range grazing - Riparian and/or Upland

Natural Sources

Grazing related Sources

Agriculture

Individual Active NPDES Permits:

TMDL (s) Completed: TMDL for pH and conductivity

HUC: 13020203

Rio Grande-Albuquerque

Rio Grande (Alameda Bridge to Santa Ana Pueblo bnd)

Rio Grande-Albuquerque

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2105.1_00	11.66	20.6.4.106	1	31-Dec-00	Rio Grande silvery minnow

Impaired Designated Use (s):

secondary contact
irrigation

Attainment status:
Partially supporting
Partially supporting

Assessment information: Probable Causes of Impairment:

Magnitude: Moderate

Fecal Coliform

Probable Sources of Impairment:

Urban Runoff/Storm Sewers
Municipal Point Sources

Individual Active NPDES Permits:

Permit No: Permit Facility Name:

NM0030228 Reddy Ice/Packaged Ice Corp.

NM0029602 Rio Rancho, City of/No. 3

NM0027987 Rio Rancho, City of/No. 2

NM0027863 Sandia Peak Ski Company/Sandia Peak

NM0023485 Bernalillo, City Of/WWTP

NM0000124 Public Service Co. of NM/Reeves Station

TMDL (s) Completed: TMDL for fecal coliform

Rio Grande (Isleta Pueblo bnd to Alameda Street Bridge)

Rio Grande-Albuquerque

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2105_50	20.4	20.6.4.105	1	31-Dec-00	Rio Grande silvery minnow

Impaired Designated Use (s): Attainment status:

irrigation Partially supporting
secondary contact Partially supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Fecal Coliform

Moderate

Probable Sources of Impairment: Urban Runoff/Storm Sewers Municipal Point Sources

Individual Active NPDES Permits:

Permit No: Permit Facility Name:

NM0030384 PNM/Person Station

NM0030376 Delta Person Generating Station NM0022250 Albuquerque, City Of/WWTP

TMDL (s) Completed: TMDL for fecal coliform

HUC: 13020204 Rio Puerco

Nacimiento Creek (USFS bnd to San Gregorio Reservoir)

Rio Puerco

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2107.A_42	4.6	20.6.4.109	4	31-Dec-17	No

Impaired Designated Use (s): Attainment status: coldwater fishery Partially supporting

Assessment information: Probable Causes of Impairment:

Magnitude: Moderate Moderate

Stream Bottom Deposits
Plant Nutrients

Probable Sources of Impairment:
Removal of Riparian Vegetation
Range grazing - Riparian and/or Upland

Habitat Modification (other than Hydromodification)

Grazing related Sources

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

TMDL (s) Completed:

Rio Puerco (Rito Olguin to headwaters)

Rio Puerco

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2107.A_40	39.6	20.6.4.109	4	31-Dec-06	No

Impaired Designated Use (s): Attainment status: coldwater fishery Partially supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Temperature

Moderate Moderate

Stream Bottom Deposits

Probable Sources of Impairment: Removal of Riparian Vegetation

Range grazing - Riparian and/or Upland Highway Maintenance and Runoff

Habitat Modification (other than Hydromodification)

Grazing related Sources

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

Permit No: Permit Facility Name:

NM0024848 Cuba, Village of/WWTP

Rito Leche (Perennial reaches above Rio Puerco)

Rio Puerco

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2107.A_43	2.9	20.6.4.109	4	31-Dec-17	No

Impaired Designated Use (s): Attainment status: coldwater fishery Partially supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Stream Bottom Deposits

Moderate

Probable Sources of Impairment:
Removal of Riparian Vegetation
Range grazing - Riparian and/or Upland

Habitat Modification (other than Hydromodification)

Grazing related Sources

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

TMDL (s) Completed:

San Pablo Canyon (Rio Puerco to headwaters)

Rio Puerco

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2107.A_41	11.5	20.6.4.109	4	31-Dec-06	No

Impaired Designated Use (s): Attainment status: coldwater fishery Partially supporting

Assessment information: Probable Causes of Impairment:

Magnitude: Moderate Moderate

Stream Bottom Deposits
Plant Nutrients

Probable Sources of Impairment:

Surface Mining Resource Extraction

Removal of Riparian Vegetation

Range grazing - Riparian and/or Upland

Habitat Modification (other than Hydromodification)

Grazing related Sources

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

HUC: 13020207 Rio San Jose

Bluewater Creek (Navajo Nation bnd to headwaters)

Rio San Jose

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2107.A_01	17.1	20.6.4.109	3	31-Dec-17	No

Impaired Designated Use (s): Attainment status: coldwater fishery Partially supporting

Assessment information: Probable Causes of Impairment:

Probable Causes of Impairment:Magnitude:TurbidityModerateTemperatureModerateStream Bottom DepositsModerateAluminum - acuteModerate

Probable Sources of Impairment:

Silviculture

Removal of Riparian Vegetation

Range grazing - Riparian and/or Upland Logging Road Construction/Maintenance Harvesting, Restoration, Residue Management Habitat Modification (other than Hydromodification)

Grazing related Sources

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

TMDL (s) Completed:

Bluewater Creek (Rio San Jose to Navajo Nation bnd)

Rio San Jose

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2107.A_00	2.4	20.6.4.109	4	31-Dec-17	No

Impaired Designated Use (s): Attainment status: coldwater fishery Partially supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Plant Nutrients

Moderate

Probable Sources of Impairment: Removal of Riparian Vegetation

Range grazing - Riparian and/or Upland

Habitat Modification (other than Hydromodification)

Grazing related Sources

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

Rio Moquino (Laguna Pueblo to Seboyettia Creek)

Rio San Jose

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2107.A_10	3	20.6.4.109	4	31-Dec-17	No

Impaired Designated Use (s): Attainment status: coldwater fishery Not supporting

Assessment information: Probable Causes of Impairment:

Magnitude: Moderate

Stream Bottom Deposits

Moderate

Probable Sources of Impairment:

Surface Mining
Resource Extraction

Removal of Riparian Vegetation

Mine Tailings

Temperature

Habitat Modification (other than Hydromodification)

Individual Active NPDES Permits:

TMDL (s) Completed:

Rio Paguate (Laguna Pueblo bnd to headwaters)

Rio San Jose

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2107.A_30	10.7	20.6.4.109	3	31-Dec-17	No

Impaired Designated Use (s): Attainment status: coldwater fishery Partially supporting

Assessment information: Probable Causes of Impairment:

Probable Causes of Impairment:Magnitude:TemperatureModerateStream Bottom DepositsModerateSelenium - chronicModerate

Probable Sources of Impairment:

Surface Mining Source Unknown Resource Extraction

Removal of Riparian Vegetation

Mine Tailings

Habitat Modification (other than Hydromodification) Bank or Shoreline Modification/Destabilization

Abandoned mining

Individual Active NPDES Permits:

HUC: 13020211

Elephant Butte Reservoir

Alamosa Creek (Perennial reaches abv Monticello diversion)

Elephant Butte Reservoir

Magnitude:

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2103.A_30	13.4	20.6.4.103	1	31-Dec-17	Alamosa springsnail (in springs)

Impaired Designated Use (s): Attainment status:

warmwater fishery Partially supporting Partially supporting marginal coldwater fishery

Assessment information: **Probable Causes of Impairment:**

Stream Bottom Deposits Moderate

Probable Sources of Impairment:

Source Unknown Road directly in stream

Individual Active NPDES Permits:

TMDL (s) Completed:

Elephant Butte Reservoir

Elephant Butte Reservoir

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2104_00	6516.56	20.6.4.104	8	31-Dec-17	No

Impaired Designated Use (s): Attainment status:

warmwater fishery Not supporting

Assessment information: **Probable Causes of Impairment:**

Magnitude: Moderate

Mercury in fish tissue

Probable Sources of Impairment:

Source Unknown

Range grazing - Riparian and/or Upland

Grazing related Sources Atmospheric Deposition

Agriculture

Individual Active NPDES Permits: Permit No: **Permit Facility Name:**

> NM0024937 NM State Parks & Rec. Commission/Elephant Butte

HUC: 13030101 Caballo

Caballo Reservoir Caballo

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2102.B_00	3019.55	20.6.4.102	8	31-Dec-17	No

Impaired Designated Use (s): Attainment status: warmwater fishery Not supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Mercury in fish tissue

Moderate

Probable Sources of Impairment:

Source Unknown

Recreation and Tourism Activities (other than Boating -

see 7900)

Range grazing - Riparian and/or Upland

Grazing related Sources Atmospheric Deposition

Agriculture

Individual Active NPDES Permits:

TMDL (s) Completed:

Percha Creek (Perenniel reaches Caballo R to M Fork)

Caballo

1	Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
	NM-2103.A_20	18.41	20.6.4.103	8	31-Dec-17	No

Impaired Designated Use (s):Attainment status:marginal coldwater fisheryPartially supportingwarmwater fisheryPartially supporting

Assessment information: Probable Causes of Impairment:

Magnitude: Moderate

Stream Bottom Deposits

Probable Sources of Impairment:

Source Unknown

Individual Active NPDES Permits:

HUC: 13030202 Mimbres

Bear Canyon Reservoir

Mimbres

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2504_30	8.63	20.6.4.504	8	31-Dec-17	No

Impaired Designated Use (s): Attainment status: coldwater fishery Not supporting

Assessment information: Probable Causes of Impairment:

Probable Causes of Impairment:Magnitude:Plant NutrientsModerateMercury in fish tissueModerateDissolved oxygenModerateBottom DepositsModerate

Probable Sources of Impairment: Removal of Riparian Vegetation

Range grazing - Riparian and/or Upland

Habitat Modification (other than Hydromodification)

Grazing related Sources

Bank or Shoreline Modification/Destabilization

Atmospheric Deposition

Agriculture

Individual Active NPDES Permits:

TMDL (s) Completed:

Cold Springs Creek (Hot Springs Creek to headwaters)

Mimbres

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2803_11	9.71	20.6.4.803	3	31-Dec-17	No

Impaired Designated Use (s): Attainment status: coldwater fishery Not supporting

Assessment information: Probable Causes of Impairment:

Probable Causes of Impairment:Magnitude:Zinc - acuteModerateCopper - acuteModerate

Probable Sources of Impairment:

Subsurface Mining Resource Extraction Mine Tailings

Individual Active NPDES Permits:

Gallinas Creek (Mimbres River to headwaters)

Mimbres

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2803_20	20.27	20.6.4.803	4	31-Dec-17	No

Impaired Designated Use (s): Attainment status: coldwater fishery Partially supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Temperature

Moderate

Probable Sources of Impairment:

Resource Extraction

Removal of Riparian Vegetation

Range grazing - Riparian and/or Upland

Natural Sources

Irrigated Crop Production

Habitat Modification (other than Hydromodification)

Grazing related Sources Crop-related Sources

Agriculture

Abandoned mining

Individual Active NPDES Permits:

TMDL (s) Completed:

Hot Springs Creek (Mimbres River to headwaters)

Mimbres

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2803_10	10.52	20.6.4.803	4	31-Dec-17	No

Impaired Designated Use (s): Attainment status: coldwater fishery Not supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Cause Unknown

Moderate

Probable Sources of Impairment:

Source Unknown

Individual Active NPDES Permits:

Mimbres River (Perennial reaches below Sheppard Canyon)

Mimbres

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2803_00	12.5	20.6.4.803	1	31-Dec-17	No

Impaired Designated Use (s): Attainment status: irrigation Not supporting

Assessment information: Probable Causes of Impairment:

Magnitude: Moderate Moderate

Stream Bottom Deposits

Probable Sources of Impairment:Range grazing - Riparian and/or Upland

Irrigated Crop Production

Hydromodification
Grazing related Sources

Dredging

Temperature

Crop-related Sources

Agriculture

Individual Active NPDES Permits:

Permit No: Permit Facility Name:
NM0020435 Chino Mines Company

TMDL (s) Completed:

Mimbres River (Sheppard Canyon to Cooney Campground)

Mimbres

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2804_00	14.27	20.6.4.804	1	31-Dec-17	Chihuahua chub

Impaired Designated Use (s): Attainment status:
high quality coldwater fishery Not supporting

Assessment information: Probable Causes of Impairment:

Probable Causes of Impairment:Magnitude:TemperatureModerateStream Bottom DepositsModerateDissolved oxygenModerate

Probable Sources of Impairment:

Resource Extraction

Removal of Riparian Vegetation

Range grazing - Riparian and/or Upland

Hydromodification

Habitat Modification (other than Hydromodification)

Grazing related Sources

Dredging Dredge Mining Agriculture

Individual Active NPDES Permits:

Tularosa Valley HUC: 13050003

Three Rivers (Perennial HWY 54 to USFS except Mescalero)

Tularosa Valley

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2802_00	3.07	20.6.4.802	4	31-Dec-17	No

Impaired Designated Use (s): Attainment status: high quality coldwater fishery Not supporting

Assessment information: **Probable Causes of Impairment:**

Magnitude: Temperature Moderate Conductivity Moderate

Probable Sources of Impairment: Range grazing - Riparian and/or Upland

Grazing related Sources

Agriculture

Individual Active NPDES Permits:

TMDL (s) Completed:

Tularosa Creek (Tularosa to Mescalero Apache bnd)

Tularosa Valley

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2801_01	13.1	20.6.4.801	4	31-Dec-17	No

Impaired Designated Use (s): Attainment status: coldwater fishery Partially supporting

Assessment information: **Probable Causes of Impairment:**

Cause Unknown

Magnitude: Moderate

Probable Sources of Impairment:

Source Unknown

Individual Active NPDES Permits:

Permit No: **Permit Facility Name:**

NM0030481 Mescalaro School

HUC: 13060001

Pecos Headwaters

Beaver Creek (Porvenir Creek to headwaters)

Pecos Headwaters

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2212_04	5.86	20.6.4.215	4	31-Dec-17	No

Impaired Designated Use (s): Attainment status:
high quality coldwater fishery Partially supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Stream Bottom Deposits

Moderate

Probable Sources of Impairment:

Silviculture

Removal of Riparian Vegetation

Recreation and Tourism Activities (other than Boating -

see 7900)

Range grazing - Riparian and/or Upland Highway Maintenance and Runoff

Harvesting, Restoration, Residue Management Habitat Modification (other than Hydromodification)

Grazing related Sources

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

TMDL (s) Completed:

Cow Creek (Pecos River to headwaters)

Pecos Headwaters

Α	ssessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
	NM-2214.A_090	37.67	20.6.4.217	4	31-Dec-17	No

Impaired Designated Use (s): Attainment status:
high quality coldwater fishery Partially supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Stream Bottom Deposits

Moderate

Probable Sources of Impairment:
Removal of Riparian Vegetation

Range grazing - Riparian and/or Upland

Natural Sources

Highway Maintenance and Runoff

Habitat Modification (other than Hydromodification)

Grazing related Sources

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

Gallinas River (Las Vegas Diversion to headwaters)

Pecos Headwaters

Magnitude:

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2212_00	24.21	20.6.4.215	3	31-Dec-17	No

Impaired Designated Use (s): Attainment status:

high quality coldwater fishery Not supporting

Assessment information: Probable Causes of Impairment:

Turbidity Moderate
Temperature Moderate
Stream Bottom Deposits Moderate
Aluminum - acute Moderate

Probable Sources of Impairment:

Removal of Riparian Vegetation

Pasture grazing - Riparian and/or Upland Off-farm Animal Holding/Management Area

Highway Maintenance and Runoff

Habitat Modification (other than Hydromodification)

Grazing related Sources

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

Gallinas River (San Augustin to Las Vegas Diversion)

Pecos Headwaters

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2213_21	16.44	20.6.4.216	6	31-Dec-17	No

Impaired Designated Use (s): Attainment status:
marginal coldwater fishery Not supporting

Assessment information: Probable Causes of Impairment: Magnitude:

Unknown toxicity Moderate
Total Ammonia Moderate
Stream Bottom Deposits Moderate

Probable Sources of Impairment:

Urban Runoff/Storm Sewers

Source Unknown

Removal of Riparian Vegetation

Range grazing - Riparian and/or Upland Onsite Wastewater Systems (Septic Tanks)

Municipal Point Sources

Land Disposal Hydromodification

Habitat Modification (other than Hydromodification)

Grazing related Sources
Flow Regulation/Modification

Channelization

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

Permit No: Permit Facility Name:

NM0030341 Las Vegas, City of/Water Treatment Plant

NM0028827 Las Vegas WWTP

TMDL (s) Completed:

Holy Ghost Creek (Pecos River to headwaters)

Pecos Headwaters

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2214.A_020	6.92	20.6.4.217	3	31-Dec-17	No

Impaired Designated Use (s):

Attainment status:

high quality coldwater fishery

Partially supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Aluminum - chronic Moderate

Probable Sources of Impairment: Removal of Riparian Vegetation

Recreation and Tourism Activities (other than Boating -

see 7900)

Highway Maintenance and Runoff

Habitat Modification (other than Hydromodification)

Individual Active NPDES Permits:

Pecos River (Alamitos Canyon to Willow Creek)

Pecos Headwaters

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2214.A_002	16.17	20.6.4.217	2	31-Dec-17	No

Impaired Designated Use (s): Attainment status:
high quality coldwater fishery Partially supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Turbidity

Moderate

Probable Sources of Impairment:

Land Development

Bank or Shoreline Modification/Destabilization

Construction

Grazing related Sources

Habitat Modification (other than Hydromodification)

Hazardous Waste

Agriculture

Highway/Road/Bridge Construction

Road/ Parking lot runoff

Land Disposal Mill Tailings Mine Tailings

Range grazing - Riparian and/or Upland

Removal of Riparian Vegetation

Resource Extraction

Highway Maintenance and Runoff

Individual Active NPDES Permits:

Permit No: Permit Facility Name:

NM0030121 NMG&FD/Lisboa Fish Hatchery

Pecos River (Canon del Oso to Alamitos Canyon)

Pecos Headwaters

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2213_00	66.54	20.6.4.216	6	31-Dec-17	No

Impaired Designated Use (s): Attainment status: marginal coldwater fishery Partially supporting

Assessment information: **Probable Causes of Impairment:**

Magnitude:

Stream Bottom Deposits

Moderate

Probable Sources of Impairment:

Removal of Riparian Vegetation

Recreation and Tourism Activities (other than Boating -

see 7900)

Range grazing - Riparian and/or Upland

Municipal Point Sources

Habitat Modification (other than Hydromodification)

Grazing related Sources

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

Permit No: **Permit Facility Name:**

NM0029041 Pecos, Village of/WWTP

NM0028363 San Miguel Co./Operation Breakthrough Housing

TMDL (s) Completed:

Pecos River (Sumner Reservoir to Canon del Oso)

Pecos Headwaters

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2211.A_00	102.79	20.6.4.211	5	31-Dec-17	No

Impaired Designated Use (s): Attainment status: limited warmwater fishery Partially supporting

Assessment information: **Probable Causes of Impairment:**

Magnitude: Moderate

Stream Bottom Deposits

Aluminum - chronic

Moderate

Probable Sources of Impairment:

Range grazing - Riparian and/or Upland

Natural Sources Hydromodification Grazing related Sources

Flow Regulation/Modification

Agriculture

Individual Active NPDES Permits:

Permit No: **Permit Facility Name:**

NM0030155 NMG&FD/Rock Lake Fish Hatchery

Rio Mora (Pecos River to headwaters)

Pecos Headwaters

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2214.A_040	17.95	20.6.4.217	4	31-Dec-17	No

Impaired Designated Use (s): Attainment status:
high quality coldwater fishery Partially supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Stream Bottom Deposits

Moderate

Probable Sources of Impairment: Removal of Riparian Vegetation

Recreation and Tourism Activities (other than Boating -

see 7900)

Range grazing - Riparian and/or Upland

Habitat Modification (other than Hydromodification)

Grazing related Sources

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

TMDL (s) Completed:

Santa Rosa Reservoir

Pecos Headwaters

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2211.B_00	1500	20.6.4.211	8	31-Dec-17	No

Impaired Designated Use (s): Attainment status:

limited warmwater fishery Not supporting

Assessment information: Probable Causes of Impairment:

Magnitude: Moderate Moderate

Moderate

Mercury in fish tissue Bottom Deposits

Probable Sources of Impairment:

Source Unknown

Plant Nutrients

Road/ Parking lot runoff

Range grazing - Riparian and/or Upland

Grazing related Sources Atmospheric Deposition

Agriculture

Individual Active NPDES Permits:

Sumner Reservoir Pecos Headwaters

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2210_00	4277.79	20.6.4.210	8	31-Dec-17	No

Impaired Designated Use (s): Attainment status:

warmwater fishery Not supporting

Assessment information: Probable Causes of Impairment: Magnitude:

Plant Nutrients Moderate
Mercury in fish tissue Moderate
Bottom Deposits Moderate

Probable Sources of Impairment:

Source Unknown

Removal of Riparian Vegetation

Recreation and Tourism Activities (other than Boating -

see 7900)

Range grazing - Riparian and/or Upland

Habitat Modification (other than Hydromodification)

Grazing related Sources

Bank or Shoreline Modification/Destabilization

Atmospheric Deposition

Agriculture

Individual Active NPDES Permits:

Tecolote Creek (Village of Tecolote to headwaters)

Pecos Headwaters

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2212_10	26.4	20.6.4.215	4	31-Dec-17	No

Impaired Designated Use (s): Attainment status:

high quality coldwater fishery Not supporting

Assessment information: Probable Causes of Impairment:

Probable Causes of Impairment:Magnitude:TurbidityModerateTemperatureModerateStream Bottom DepositsModerateConductivityModerate

Probable Sources of Impairment:

Removal of Riparian Vegetation

Range grazing - Riparian and/or Upland Onsite Wastewater Systems (Septic Tanks)

Land Disposal Land Development

Highway Maintenance and Runoff

Habitat Modification (other than Hydromodification)

Grazing related Sources

Construction

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

Willow Creek (Pecos River to headwaters)

Pecos Headwaters

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2214.A 030	5.76	20.6.4.217	4	31-Dec-17	No

Impaired Designated Use (s): Attainment status:
high quality coldwater fishery Partially supporting

Assessment information: Probable Causes of Impairment:

Probable Causes of Impairment:Magnitude:Zinc - chronicModerateZinc - acuteModerateTurbidityModerateStream Bottom DepositsModerateConductivityModerateCadmium - chronicModerate

Probable Sources of Impairment:

Source Unknown
Resource Extraction

Removal of Riparian Vegetation

Mine Tailings

Highway Maintenance and Runoff

Habitat Modification (other than Hydromodification) Bank or Shoreline Modification/Destabilization

Individual Active NPDES Permits:

TMDL (s) Completed:

Wright Canyon Creek (Tecolote Creek to headwaters)

Pecos Headwaters

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2212_18	2.05	20.6.4.215	6	31-Dec-17	No

Impaired Designated Use (s):

Attainment status:

high quality coldwater fishery

Partially supporting

Assessment information: Probable Causes of Impairment:

Probable Causes of Impairment:Magnitude:TurbidityModerateStream Bottom DepositsModerate

Probable Sources of Impairment:

Recreation and Tourism Activities (other than Boating -

see 7900)

Range grazing - Riparian and/or Upland Highway Maintenance and Runoff

Grazing related Sources

Agriculture

Individual Active NPDES Permits:

HUC: 13060008 Rio Hondo

Alto Lake Rio Hondo

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2209.B_30	11.16	20.6.4.209	8	31-Dec-17	No

Impaired Designated Use (s): Attainment status:

fish culture Not supporting high quality coldwater fishery Not supporting

Assessment information: Probable Causes of Impairment: Magnitude:

Copper - acute Moderate

Probable Sources of Impairment:
Pesticide application (cooper sulfate)

Individual Active NPDES Permits:

TMDL (s) Completed:

Rio Bonito (Rio Ruidoso to Angus Canyon)

Rio Hondo

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2208_10	33.63	20.6.4.208	4	31-Dec-17	No

Impaired Designated Use (s):Attainment status:irrigationPartially supportingcoldwater fisheryPartially supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Stream Bottom Deposits

Moderate

Probable Sources of Impairment: Removal of Riparian Vegetation

Range grazing - Riparian and/or Upland

Hydromodification

Highway Maintenance and Runoff

Habitat Modification (other than Hydromodification)

Grazing related Sources Flow Regulation/Modification

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

Rio Hondo (Perennial reaches Pecos R to Rio Ruidoso)

Rio Hondo

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2208_30	8	20.6.4.208	4	31-Dec-17	No

Impaired Designated Use (s): Attainment status: coldwater fishery Partially supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Cause Unknown

Moderate

Probable Sources of Impairment:

Source Unknown

Individual Active NPDES Permits:

TMDL (s) Completed:

Rio Ruidoso (Rio Bonito to Seeping Springs Lake)

Rio Hondo

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2208_20	19.63	20.6.4.208	2	31-Dec-17	No

Impaired Designated Use (s): Attainment status: coldwater fishery Partially supporting

Assessment information: Probable Causes of Impairment:

Probable Causes of Impairment:Magnitude:Stream Bottom DepositsModeratePlant NutrientsModerate

Probable Sources of Impairment: Removal of Riparian Vegetation

Range grazing - Riparian and/or Upland

Municipal Point Sources Hydromodification

Highway Maintenance and Runoff

Habitat Modification (other than Hydromodification)

Grazing related Sources Flow Regulation/Modification

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

Permit No: Permit Facility Name:

NM0029165 Ruidoso City of/Ruidoso Downs WWTP

Rio Ruidoso (Seeping Springs Lake to Mescalero Apache bnd)

Rio Hondo

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2209.A_20	12.4	20.6.4.209	2	31-Dec-17	No

Impaired Designated Use (s):

high quality coldwater fishery

Partially supporting

Assessment information: Probable Causes of Impairment:

Probable Causes of Impairment:Magnitude:TurbidityModerateTemperatureModerateStream Bottom DepositsModeratePlant NutrientsModerate

Probable Sources of Impairment:

Removal of Riparian Vegetation

Recreation and Tourism Activities (other than Boating -

see 7900)

Range grazing - Riparian and/or Upland Onsite Wastewater Systems (Septic Tanks)

Land Disposal Land Development

Habitat Modification (other than Hydromodification)

Grazing related Sources

Construction

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

HUC: 13060010 Rio Penasco

Rio Peñasco (HWY 24 to headwaters)

Rio Penasco

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2208_00	45.7	20.6.4.208	2	31-Dec-17	No

Impaired Designated Use (s): Attainment status: coldwater fishery Partially supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Stream Bottom Deposits

Moderate

Probable Sources of Impairment:Removal of Riparian Vegetation
Range grazing - Riparian and/or Upland

Highway Maintenance and Runoff

Habitat Modification (other than Hydromodification)

Grazing related Sources

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

Permit No: Permit Facility Name:

NM0028886 Sacramento Methodist Assembly

NM0023370 Cloudcroft, Village of

TMDL (s) Completed:

Rio Peñasco (Pecos River to HWY 24)

Rio Penasco

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2206.A_10	63.7	20.6.4.206	2	31-Dec-17	No

Impaired Designated Use (s): Attainment status:

warmwater fishery Partially supporting

Assessment information: Probable Causes of In

Probable Causes of Impairment: Magnitude:

Stream Bottom Deposits

Moderate

Probable Sources of Impairment: Removal of Riparian Vegetation

Range grazing - Riparian and/or Upland Highway Maintenance and Runoff

Habitat Modification (other than Hydromodification)

Grazing related Sources

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

HUC: 13060011 U

Upper Pecos-Black

Avalon Reservoir Upper Pecos-Black

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2204.B_00	497.7	20.6.4.204	8	31-Dec-17	No

Impaired Designated Use (s): Attainment status:

warmwater fishery Not supporting

Assessment information: Probable Causes of Impairment:

Magnitude: Moderate

Mercury in fish tissue

Probable Sources of Impairment:

Source Unknown

Atmospheric Deposition

Individual Active NPDES Permits:

TMDL (s) Completed:

Black River (Pecos River to headwaters)

Upper Pecos-Black

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2202.A_10	16.9	20.6.4.202	8	31-Dec-17	No

Impaired Designated Use (s): Attainment status:
warmwater fishery Partially supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Cause Unknown

Moderate

Probable Sources of Impairment:

Source Unknown

Individual Active NPDES Permits:

Brantley Reservoir Upper Pecos-Black

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2205_00	3058.67	20.6.4.205	8	31-Dec-17	No

Impaired Designated Use (s): Attainment status:

warmwater fishery Not supporting

Assessment information: Probable Causes of Impairment:

Probable Causes of Impairment: Magnitude:

Mercury in fish tissue Moderate

Probable Sources of Impairment:

Source Unknown
Atmospheric Deposition

Individual Active NPDES Permits:

TMDL (s) Completed:

Laguna Gatuna Upper Pecos-Black

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-9000.B 055	294.76	unclassified	8	31-Dec-17	No

Impaired Designated Use (s): Attainment status:

wildlife habitat Not supporting livestock watering Not supporting

Assessment information: Probable Causes of Impairment: Magnitude:

Toxic substances Moderate

Probable Sources of Impairment:

Resource Extraction

Individual Active NPDES Permits:

TMDL (s) Completed:

Laguna Quatro Upper Pecos-Black

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-9000.B_059	150	unclassified	8	31-Dec-17	No

Impaired Designated Use (s): Attainment status:

wildlife habitat Not supporting livestock watering Not supporting

Assessment information: Probable Causes of Impairment: Magnitude:

Toxic substances Moderate

Probable Sources of Impairment:

Resource Extraction

Individual Active NPDES Permits:

Laguna Tres Upper Pecos-Black

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-9000.B_061	430	unclassified	8	31-Dec-17	No

Impaired Designated Use (s): Attainment status:

livestock watering Not supporting wildlife habitat Not supporting

Assessment information: Probable Causes of Impairment:

Probable Causes of Impairment: Magnitude:
Toxic substances Moderate

Probable Sources of Impairment:

Resource Extraction
Petroleum Activities

Individual Active NPDES Permits:

TMDL (s) Completed:

Laguna Uno Upper Pecos-Black

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-9000.B_066	600	unclassified	8	31-Dec-17	No

Impaired Designated Use (s): Attainment status:

wildlife habitat Not supporting livestock watering Not supporting

Assessment information: Probable Causes of Impairment: Magnitude:

Toxic substances Moderate

Probable Sources of Impairment:

Resource Extraction

Individual Active NPDES Permits:

Pecos River (Black River to Tansil Lake)

Upper Pecos-Black

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2202.A_00	19.18	20.6.4.202	6	31-Dec-17	No

Impaired Designated Use (s): Attainment status:

warmwater fishery Partially supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Stream Bottom Deposits

Moderate

Probable Sources of Impairment:

Source Unknown

Removal of Riparian Vegetation

Range grazing - Riparian and/or Upland

Municipal Point Sources Irrigated Crop Production

Habitat Modification (other than Hydromodification)

Grazing related Sources Crop-related Sources

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

Permit No: Permit Facility Name:

NM0026395 Carlsbad, City Of WWTP

Pecos River (TX border to Black River)

Upper Pecos-Black

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2201_00	30.18	20.6.4.201	8	31-Dec-17	No

Impaired Designated Use (s): Attainment status:

livestock watering Not supporting irrigation Not supporting warmwater fishery Not supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Stream Bottom Deposits

Moderate

Probable Sources of Impairment: Removal of Riparian Vegetation

Range grazing - Riparian and/or Upland

Natural Sources

Irrigated Crop Production

Hydromodification

Habitat Modification (other than Hydromodification)

Grazing related Sources
Flow Regulation/Modification

Crop-related Sources

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

Permit No: Permit Facility Name:

NM0029131 Southwestern Public Service Co./Dc Terminal

Sitting Bull Creek (Last Chance Canyon to Sitting Bull Spr)

Upper Pecos-Black

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-9000.A_007	3	unclassified	8	31-Dec-17	No

Impaired Designated Use (s):

secondary contact

warmwater fishery

Attainment status:

Partially supporting

Partially supporting

Assessment information: Probable Causes of Impairment:

Probable Causes of Impairment:Magnitude:TemperatureModerateStream Bottom DepositsModeratePlant NutrientsModerateFecal ColiformModerate

Probable Sources of Impairment:

Road/ Parking lot runoff

Removal of Riparian Vegetation

Range grazing - Riparian and/or Upland Onsite Wastewater Systems (Septic Tanks)

Land Disposal

Habitat Modification (other than Hydromodification)

Grazing related Sources

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

TMDL (s) Completed:

Tansil Lake (Carlsbad Municipal Lake)

Upper Pecos-Black

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2203.B_00	29.02	20.6.4.203	8	31-Dec-17	No

Impaired Designated Use (s): Attainment status: warmwater fishery Not supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Mercury in fish tissue

Moderate

Probable Sources of Impairment:

Source Unknown

Atmospheric Deposition

Individual Active NPDES Permits:

Upper San Juan HUC: 14080101

Upper San Juan Navajo Reservoir

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2406_00	13151.19	20.6.4.406	8	31-Dec-17	No

Impaired Designated Use (s): Attainment status:

warmwater fishery Not supporting coldwater fishery Not supporting

Assessment information: Probable Causes of Impairment: Magnitude: Moderate

Mercury in fish tissue

Probable Sources of Impairment:

Source Unknown Atmospheric Deposition

Individual Active NPDES Permits:

San Juan River (Animas River to Cañon Largo)

Upper San Juan

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2401_00	21.44	20.6.4.401	1	31-Dec-04	Colorado pikeminnow

Impaired Designated Use (s): Attainment status:

warmwater fishery Not supporting marginal coldwater fishery Not supporting

Assessment information: **Probable Causes of Impairment:**

Magnitude: Moderate Moderate

Stream Bottom Deposits Mercury in fish tissue Fecal Coliform Moderate

Probable Sources of Impairment:

Urban Runoff/Storm Sewers

Septage Disposal Resource Extraction

Removal of Riparian Vegetation

Range grazing - Riparian and/or Upland

Petroleum Activities

Onsite Wastewater Systems (Septic Tanks)

Municipal Point Sources

Land Disposal

Irrigated Crop Production

Habitat Modification (other than Hydromodification)

Grazing related Sources Crop-related Sources

Bank or Shoreline Modification/Destabilization

Agriculture Permit No:

Individual Active NPDES Permits:

Permit Facility Name:

NM0030473 San Juan County/ McGee Park WWTP NM0028142 Bloomfield Municipal School District #6

NM0020770 Bloomfield, City of/WWTP

San Juan River (Cañon Largo to Navajo Reservoir)

Upper San Juan

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2405_10	19.53	20.6.4.405	1	31-Dec-04	Colorado pikeminnow

Impaired Designated Use (s): Attainment status:

high quality coldwater fishery Not supporting

Assessment information: Probable Causes of Impairment:

Probable Causes of Impairment:Magnitude:TurbidityModerateStream Bottom DepositsModerateMercury in fish tissueModerate

Probable Sources of Impairment:

Septage Disposal Resource Extraction

Removal of Riparian Vegetation

Range grazing - Riparian and/or Upland

Petroleum Activities

Onsite Wastewater Systems (Septic Tanks)

Land Disposal

Habitat Modification (other than Hydromodification)

Grazing related Sources

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

HUC: 14080104 Animas

Animas River (Estes Arroyo to CO border)

Animas

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2404_00	19.6	20.6.4.404	4	31-Dec-04	No

Impaired Designated Use (s): Attainment status: coldwater fishery Partially supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Stream Bottom Deposits

Moderate

Probable Sources of Impairment: Urban Runoff/Storm Sewers

Resource Extraction

Removal of Riparian Vegetation

Range grazing - Riparian and/or Upland

Petroleum Activities Irrigated Crop Production Hydromodification

Habitat Modification (other than Hydromodification)

Grazing related Sources
Crop-related Sources
Channelization

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

Animas River (San Juan River to Estes Arroyo)

Animas

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2403.A_00	16.92	20.6.4.403	6	31-Dec-04	No

Impaired Designated Use (s):

warmwater fishery

marginal coldwater fishery

Attainment status:

Partially supporting

Partially supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Stream Bottom Deposits

Moderate

Probable Sources of Impairment:

Urban Runoff/Storm Sewers Source Unknown

Resource Extraction

Removal of Riparian Vegetation

Petroleum Activities

Onsite Wastewater Systems (Septic Tanks)

Municipal Point Sources

Land Disposal

Industrial Point Sources Hydromodification

Habitat Modification (other than Hydromodification)

Channelization

Bank or Shoreline Modification/Destabilization

Individual Active NPDES Permits:

Permit No: Permit Facility Name:

NM0028258 Farmington Sand & Gravel Co

NM0020168 City of Aztec

NM0000043 Farmington, City of/Animas Steam Plant

TMDL (s) Completed:

Lake Farmington (Beeline Reservoir)

Animas

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-9000.B_006	198	unclassified	8	31-Dec-17	No

Impaired Designated Use (s): Attainment status: warmwater fishery Not supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Mercury in fish tissue

Moderate

Probable Sources of Impairment:

Atmospheric Deposition

Individual Active NPDES Permits:

HUC: 14080105 Middle San Juan

La Plata River (San Juan River to CO border)

Middle San Juan

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2402.A_00	25.33	20.6.4.402	6	31-Dec-04	No

Impaired Designated Use (s):Attainment status:limited warmwater fisheryPartially supportingmarginal coldwater fisheryPartially supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Plant Nutrients

Moderate

Probable Sources of Impairment:

Removal of Riparian Vegetation

Range grazing - Riparian and/or Upland Onsite Wastewater Systems (Septic Tanks)

Land Disposal

Intensive Animal Feeding Operations

Industrial Point Sources

Habitat Modification (other than Hydromodification)

Grazing related Sources

Confined Animal Feeding Operations (NPS)
Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

Permit No: Permit Facility Name:

NM0029505 San Juan Coal Company/La Plata Mine

San Juan River (Navajo bnd at Hogback to Animas River)

Middle San Juan

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2401_10	32.27	20.6.4.401	1	31-Dec-04	Colorado pikeminnow

Impaired Designated Use (s): Attainment status:
marginal coldwater fishery Partially supporting

warmwater fishery Partially supporting

Assessment information: Probable Causes of Impairment:

Probable Causes of Impairment:Magnitude:Stream Bottom DepositsModerateMercury in fish tissueModerate

Probable Sources of Impairment:

Landfills Agriculture

Bank or Shoreline Modification/Destabilization

Crop-related Sources
Grazing related Sources

Habitat Modification (other than Hydromodification)

Industrial Point Sources Abandoned mining Land Disposal Source Unknown

Municipal Point Sources

Onsite Wastewater Systems (Septic Tanks)

Petroleum Activities

Range grazing - Riparian and/or Upland

Removal of Riparian Vegetation

Resource Extraction
Irrigated Crop Production

Individual Active NPDES Permits:

Permit No: Permit Facility Name:

NM0029319 Central Consolidated School District No 22 NM0029025 Harper Valley Home Owners Association

NM0027995 Four Corners Materials Inc.

NM0020800 USDI-BIA/Nenahnezad Boarding

NM0020583 Farmington, City of/WWTP

NM0000019 Arizona Public Service Company

HUC: 15020003 Carrizo Wash

Quemado Lake Carrizo Wash

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-9000.B_096	111.89	unclassified	8	31-Dec-17	No

Impaired Designated Use (s): Attainment status: coldwater fishery Not supporting

Assessment information: Probable Causes of Impairment:

Magnitude: Moderate Moderate

Plant Nutrients Bottom Deposits

Probable Sources of Impairment:

Silviculture

Removal of Riparian Vegetation

Recreation and Tourism Activities (other than Boating -

see 7900)

Range grazing - Riparian and/or Upland

Natural Sources

Harvesting, Restoration, Residue Management Habitat Modification (other than Hydromodification)

Grazing related Sources

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

HUC: 15020004 Zuni

McGaffey Lake Zuni

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-9000.B_083	10.94	unclassified	8	31-Dec-17	No

Impaired Designated Use (s): Attainment status:

warmwater fishery Not supporting coldwater fishery Not supporting

Assessment information: Probable Causes of Impairment: Magnitude:

Plant Nutrients Moderate pH Moderate Bottom Deposits Moderate

Probable Sources of Impairment:

Road/ Parking lot runoff

Removal of Riparian Vegetation

Natural Sources

Highway Maintenance and Runoff

Habitat Modification (other than Hydromodification) Bank or Shoreline Modification/Destabilization

Individual Active NPDES Permits:

TMDL (s) Completed:

Rio Nutria (Zuni Pueblo bnd to headwaters)

Zuni

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-9000.A_029	11.8	unclassified	5	31-Dec-17	No

Impaired Designated Use (s): Attainment status:

warmwater fishery Partially supporting

Assessment information: Probable Causes of Impairment: Magnitude:

Mercury - chronic Moderate

Probable Sources of Impairment:

Source Unknown

Individual Active NPDES Permits:

HUC: 15040001 Upper Gila

Black Canyon Creek (East Fork Gila River to headwaters)

Upper Gila

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2503_21	25.21	20.6.4.503	4	31-Dec-01	No

Impaired Designated Use (s):

high quality coldwater fishery

Not supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Temperature

Moderate

Probable Sources of Impairment: Removal of Riparian Vegetation

Recreation and Tourism Activities (other than Boating -

see 7900)

Range grazing - Riparian and/or Upland

Off-road vehicles
Natural Sources

Habitat Modification (other than Hydromodification)

Grazing related Sources

Forest Management (fire suppression)

Agriculture

Individual Active NPDES Permits:

TMDL (s) Completed: TMDL for temperature

Canyon Creek (Middle Fork Gila River to headwaters)

Upper Gila

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2503_43	14.25	20.6.4.503	4	31-Dec-01	No

Impaired Designated Use (s): Attainment status:
high quality coldwater fishery Partially supporting

Assessment information: Probable Causes of Impairment:

Magnitude: Moderate

Turbidity
Plant Nutrients

Moderate

Probable Sources of Impairment: Removal of Riparian Vegetation

Range grazing - Riparian and/or Upland

Habitat Modification (other than Hydromodification)

Grazing related Sources

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

TMDL (s) Completed: TMDL turbidity and plant nutrients

Gila River (East Fork) Upper Gila

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2503_20	26.24	20.6.4.503	1	31-Dec-01	spikedace; loach minnow; Gila trout

Impaired Designated Use (s): Attainment status:

high quality coldwater fishery Not supporting

Assessment information: **Probable Causes of Impairment:**

Magnitude:

Magnitude:

Aluminum - chronic Moderate

Probable Sources of Impairment:

Recreation and Tourism Activities (other than Boating -

see 7900)

Range grazing - Riparian and/or Upland

Off-road vehicles **Natural Sources**

Grazing related Sources

Forest Management (fire suppression)

Agriculture

Individual Active NPDES Permits:

TMDL (s) Completed: TMDL Al chronic

Gila River (Middle Fork)

Upper Gila

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2503_40	36.64	20.6.4.503	1	31-Dec-06 Proposed	spikedace

Impaired Designated Use (s): Attainment status:

high quality coldwater fishery Not supporting

Assessment information: **Probable Causes of Impairment:**

> Temperature Moderate

Probable Sources of Impairment:

Recreation and Tourism Activities (other than Boating -

see 7900) Natural Sources

Forest Management (fire suppression)

Individual Active NPDES Permits:

Gila River (West Fork below Gila Cliff Dwellings)

Upper Gila

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2503_10	4.88	20.6.4.503	1	31-Dec-06 Proposed	spikedace; loach minnow

Impaired Designated Use (s): Attainment status:

high quality coldwater fishery Not supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Temperature

Moderate

Probable Sources of Impairment:

Recreation and Tourism Activities (other than Boating -

see 7900) Off-road vehicles Natural Sources

Forest Management (fire suppression)

Individual Active NPDES Permits:

TMDL (s) Completed:

Assessment information:

Gilita Creek (Middle Fork to Willow Creek)

Upper Gila

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2503_45	6.28	20.6.4.503	4	31-Dec-06 Proposed	No

Impaired Designated Use (s): Attainment status:
high quality coldwater fishery Partially supporting

riigii quality coluwatei lishery — Fartially supporting

Probable Causes of Impairment:Magnitude:TemperatureModerateAluminum - chronicModerate

Probable Sources of Impairment:

Recreation and Tourism Activities (other than Boating -

see 7900)

Range grazing - Riparian and/or Upland

Off-road vehicles
Natural Sources
Crazing related Sources

Grazing related Sources

Forest Management (fire suppression)

Agriculture

Individual Active NPDES Permits:

Lake Roberts Upper Gila

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2504_20	68.37	20.6.4.504	8	31-Dec-17	No

Impaired Designated Use (s): Attainment status: coldwater fishery Partially supporting

Assessment information: Probable Causes of Impairment: Magnitude:

Temperature Moderate
Plant Nutrients Moderate
pH Moderate

Probable Sources of Impairment:

Road/ Parking lot runoff

Recreation and Tourism Activities (other than Boating -

see 7900) Agriculture

Individual Active NPDES Permits:

TMDL (s) Completed:

Mogollon Creek (Perennial reaches abv USGS gage)

Upper Gila

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2503_02	29.49	20.6.4.503	1	31-Dec-01	Gila trout

Impaired Designated Use (s): Attainment status:
high quality coldwater fishery Not supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Aluminum - chronic

Moderate

Probable Sources of Impairment:

Resource Extraction

Range grazing - Riparian and/or Upland

Off-road vehicles
Mill Tailings

Habitat Modification (other than Hydromodification)

Grazing related Sources

Forest Management (fire suppression)
Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

TMDL (s) Completed: TMDL Al chronic; de-list letter for SBD, chronic lead

Sapillo Creek (Gila River to Lake Roberts)

Upper Gila

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2503_04	11.88	20.6.4.503	4	31-Dec-01	spikedace; loach minnow

Impaired Designated Use (s): Attainment status:
high quality coldwater fishery Partially supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Turbidity

Moderate

Probable Sources of Impairment:

Upstream impoundments
Removal of Riparian Vegetation

Off-road vehicles

Highway Maintenance and Runoff

Habitat Modification (other than Hydromodification)

Forest Management (fire suppression)

Bank or Shoreline Modification/Destabilization

Individual Active NPDES Permits:

TMDL (s) Completed: TMDL turbidity and TOC; de-list letter for biological impairment

Taylor Creek (Beaver Creek to Wall Lake)

Upper Gila

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2503_23	2.63	20.6.4.503	3	31-Dec-01	No

Impaired Designated Use (s):

high quality coldwater fishery

Not supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Turbidity Moderate
Temperature Moderate
Aluminum - chronic Moderate

Probable Sources of Impairment:

Upstream impoundments

Recreation and Tourism Activities (other than Boating -

see 7900)

Range grazing - Riparian and/or Upland

Off-road vehicles

Grazing related Sources

Forest Management (fire suppression)

Agriculture

Individual Active NPDES Permits:

TMDL (s) Completed: TMDL temperature and Al chronic

Taylor Creek (Perennial reaches abv Wall Lake)

Upper Gila

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2503_24	19.8	20.6.4.503	4	31-Dec-06 Proposed	No

Impaired Designated Use (s): Attainment status:

Assessment information: Probable Causes of Impairment:

Probable Causes of Impairment:Magnitude:TurbidityModerateTemperatureModerateAluminum - chronicModerateAluminum - acuteModerate

Probable Sources of Impairment:

Range grazing - Riparian and/or Upland

Natural Sources

Not supporting

Grazing related Sources

Forest Management (fire suppression)

Agriculture

Individual Active NPDES Permits:

high quality coldwater fishery

TMDL (s) Completed:

Turkey Creek (Gila River to headwaters)

Upper Gila

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2503_03	16.94	20.6.4.503	4	31-Dec-06 Proposed	No

Impaired Designated Use (s):

high quality coldwater fishery

Not supporting

Assessment information: Probable Causes of Impairment:

Probable Causes of Impairment:Magnitude:TemperatureModerateDissolved oxygenModerate

Probable Sources of Impairment:

Natural Sources

Forest Management (fire suppression)

Individual Active NPDES Permits:

Wall Lake Upper Gila

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2504_10	14.33	20.6.4.504	8	31-Dec-17	No

Impaired Designated Use (s): Attainment status:

coldwater fishery Not supporting

Assessment information: Probable Causes of Impairment: Magnitude:
Plant Nutrients Moderate

Dissolved oxygen Moderate
Bottom Deposits Moderate

Probable Sources of Impairment:

Silviculture

Removal of Riparian Vegetation

Range grazing - Riparian and/or Upland

Natural Sources

Highway Maintenance and Runoff

Habitat Modification (other than Hydromodification)

Grazing related Sources

Forest Management (fire suppression)

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

HUC: 15040002 Upper Gila-Mangas

Mangas Creek (Gila River to Mangas Springs)

Upper Gila-Mangas

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2502.A_21	6.17	20.6.4.502	8	31-Dec-01	No

Impaired Designated Use (s): Attainment status:

warmwater fishery Not supporting marginal coldwater fishery Not supporting

Assessment information: Probable Causes of Impairment: Magnitude:

Plant Nutrients Moderate

Probable Sources of Impairment:

Removal of Riparian Vegetation

Recreation and Tourism Activities (other than Boating -

see 7900)

Range grazing - Riparian and/or Upland Onsite Wastewater Systems (Septic Tanks)

Off-road vehicles Natural Sources Land Disposal

Habitat Modification (other than Hydromodification)

Grazing related Sources

Bank or Shoreline Modification/Destabilization

Agriculture

Individual Active NPDES Permits:

TMDL (s) Completed: TMDL for plant nutrients; de-list letter for SBD

HUC: 15040004 San Francisco

Centerfire Creek (San Francisco R to headwaters)

San Francisco

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2603.A_50	16.12	20.6.4.603	4	31-Dec-06 Proposed	No

Impaired Designated Use (s):

high quality coldwater fishery

Not supporting

Assessment information: Probable Causes of Impairment:

Probable Causes of Impairment:Magnitude:TemperatureModeratePlant NutrientsModeratepHModerateConductivityModerate

Probable Sources of Impairment:

Recreation and Tourism Activities (other than Boating -

see 7900)

Range grazing - Riparian and/or Upland

Off-road vehicles
Natural Sources

Grazing related Sources

Forest Management (fire suppression)

Agriculture

Individual Active NPDES Permits:

TMDL (s) Completed: TMDL for plant nutrients and conductivity

Negrito Creek (South Fork)

San Francisco

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2603.A 43	14.46	20.6.4.603	4	31-Dec-01	No

Impaired Designated Use (s): Attainment status:
high quality coldwater fishery Not supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Temperature

Moderate

Probable Sources of Impairment: Removal of Riparian Vegetation

Recreation and Tourism Activities (other than Boating -

see 7900)

Range grazing - Riparian and/or Upland Highway Maintenance and Runoff

Habitat Modification (other than Hydromodification)

Grazing related Sources

Forest Management (fire suppression)

Agriculture

Individual Active NPDES Permits:

TMDL (s) Completed: TMDL for temperature

Negrito Creek (Tularosa River to confl of N and S forks)

San Francisco

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2603.A_42	12.41	20.6.4.603	4	31-Dec-06 Proposed	No

Impaired Designated Use (s): Attainment status:

high quality coldwater fishery Not supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Temperature

Moderate

Probable Sources of Impairment:

Recreation and Tourism Activities (other than Boating -

see 7900)

Pasture grazing - Riparian and/or Upland Highway Maintenance and Runoff

Grazing related Sources

Forest Management (fire suppression)

Agriculture

Individual Active NPDES Permits:

TMDL (s) Completed:

San Francisco River (Centerfire Creek to AZ border)

San Francisco

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2602_20	14.91	20.6.4.602	4	31-Dec-01	No

Impaired Designated Use (s): Attainment status:

coldwater fishery Not supporting

Assessment information: Probable Causes of Impairment:

Magnitude: Moderate Moderate

Temperature Plant Nutrients

Probable Sources of Impairment:

Range grazing - Riparian and/or Upland

Natural Sources

Grazing related Sources

Forest Management (fire suppression)

Agriculture

Individual Active NPDES Permits:

TMDL (s) Completed: TMDL for temperature and plant nutrients; de-list for turbidity

Tularosa River (San Francisco R to Apache Creek)

San Francisco

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2603.A_40	21.99	20.6.4.603	1	31-Dec-01	loach minnow

Impaired Designated Use (s): Attainment status:
high quality coldwater fishery Not supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Conductivity

Moderate

Probable Sources of Impairment:

Range grazing - Riparian and/or Upland

Natural Sources

Highway Maintenance and Runoff

Grazing related Sources

Forest Management (fire suppression)

Agriculture

Individual Active NPDES Permits:

TMDL (s) Completed: TMDL for conductivity

Whitewater Creek (San Francisco R to Whitewater Campgrd)

San Francisco

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2603.A_10	6.9	20.6.4.603	3	31-Dec-01	No

Impaired Designated Use (s):

high quality coldwater fishery

Not supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Turbidity

Moderate

Probable Sources of Impairment: Removal of Riparian Vegetation

Hydromodification

Highway Maintenance and Runoff

Habitat Modification (other than Hydromodification)

Channelization

Bank or Shoreline Modification/Destabilization

Individual Active NPDES Permits:

Permit No: Permit Facility Name:

NM0030163 NMG&FD/Glenwood Fish Hatchery

TMDL (s) Completed: TMDL for turbidity

Whitewater Creek (Whitewater Campgrd to headwaters)

San Francisco

Assessment Unit ID:	Size (mi or ac):	WQS reference:	Priority:	TMDL due:	Federal aquatic T/E species:
NM-2603.A_12	14.17	20.6.4.603	4	31-Dec-06 Proposed	No

Impaired Designated Use (s): Attainment status:

high quality coldwater fishery Not supporting

Assessment information: Probable Causes of Impairment:

Magnitude:

Aluminum - chronic

Moderate

Probable Sources of Impairment:

Recreation and Tourism Activities (other than Boating -

see 7900)

Natural Sources

Forest Management (fire suppression)

Individual Active NPDES Permits: